

Report ID:	27,168,492	Version:	3
Created:	27 Nov 2025		

		Doo:	a Candition Cuida		
	nue	<u> </u>	c Condition Guide	Created:	27 Nov 20
Make:	Skoda	Model:	Kodiaq		
Body Style:	SUV	Year:	2021		
Rego No.:	NPN241	Rego Expiry:	06 Jan 2026	Engine	
WoF Expiry:	30 Jun 2026	Odometer:	151,724 Kms	Oil level	
Good No.:	27168492	VIN:	TMBKC9NSXM8053889	Smoke & fu	
Next Service:	155060	Service History:	Yes	Engine per	formance
Note: This report is a				Noise	
This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant co	
	ection prior to purchase and		n from cold. The Vendor recommends a or an additional charge.		erformance
Key				Radiator / I	Hoses (visual
•	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmiss	ion
D = Dent PT	= Paint defect $P = Pi$	in dent SC = Stor	ne Chips	Operation	
				Noise	
	$\overline{}$			Clutch	
				CV joints	
				Wheel bea	rings
S				Brakes	
	Mr 11.			Performance	
				Hand brake	
SC	R			Tyres (lowest observed	
$\overline{}$				Left front	
				Right front	
				Left rear	
		D		Right rear	
Note: some defects a	and blemishes may not be	displayed in the diagra	im	Spare	
Body Inspection	on Comments			Suspensio	n
				Suspension	n performan
				Steering pe	erformance
				Shock abso	orbers
Conditions Duri	ing Body Inspection		Dry	Air Condit	tioning / Hea
Under Carriage	e and Under Bonnet	Inspection Comm	nents	Operation	
				Electrical /	/ Accessorie
				Head light:	S
				Tail lights	
Interior Comm	ents			Indicators	
Seats:	Average			Dashboard	d warning lig
Carpets:	Average			Wipers (fro	ont & rear)
Panels:	drivers door seal v	worn		Window w	inder FL
Dashboard:	Average		·	Window w	inder FR

		Requires	
	OK	Attention	N/A
Engine		<u> </u>	
Oil level	/		
Smoke & fumes	<b>/</b>		
Engine performance	/		
Noise	/		
Coolant condition	•		
Cooling performance	•		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			
CV joints	~		
Wheel bearings	<b>/</b>		
Brakes			
Performance	<b>/</b>		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		4	4.0 mm
Right front		4	4.0 mm
Left rear		4	4.0 mm
Right rear			4.0 mm
Spare	Yes		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	<b>/</b>		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	/		
Window winder FL	1		
Window winder FR			
Window winder RL	<b>/</b>		<del>                                     </del>
Window winder RR	~		
Rear view mirrors			
Radio (basic test only)	<i>\</i>		
	_		
CD (basic test only)  Number of keys	1	l	
•	· ·	ĺ	<u> </u>
Central locking	4		
Remote locking			
Sat. nav. (basic test only)			<del>-</del>
Reversing camera			

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	<b>✓</b> No	Km
Inspected by:	Greg Morgan			
Published by:	Francois Kleyn			
Inspection Date:	05 Nov 2025			

have read and understood
his condition quide

**General Comments** 

NAME			