

Report ID:	27,168,672	Version:	2
Created:	07 Nov 2025		


Make:	Nissan	Model:	Elgrand
Body Style:	SUV	Year:	2000
Rego No.:	GCJ482	Rego Expiry:	13 Apr 2026
WoF Expiry:	04 Nov 2025	Odometer:	144,153 Kms
Good No.:	27168672	VIN:	7AT0DH6MX11005137
Next Service:	140,000kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Paint cracked and flaking on front bumper. Right front guard inner liner is damaged. Left fog light is cracked. No tool kit. Needs Emergency silt release switch to shift from P to Drive. ( Brake pedal sensor is faulty)

Conditions During Body Inspection    Dry

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

## General Comments

No LVV cert for Powered lifter fitted in cargo. Right front door lock is not operating. 3rd row left seat had been removed. 3rd row right seat belt is jammed and seat can not be fold down. 2nd row centre seat head rest is missing. Rear wiper washer is not operating. AC is not very cold.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms
Inspected by:	Yuki Itohara
Published by:	Henry Belt
Inspection Date:	06 Nov 2025

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5.5 mm
Right front			5.5 mm
Left rear			5.5 mm
Right rear			5.5 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation		✓	
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking		✓	
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera		✓	

I have read and understood this condition guide: \_\_\_\_\_

NAME

SIGNATURE