

| • | Report ID: | 27,168,751 | Version: | 2 |
|---|------------|-------------|----------|---|
| | Created: | 20 Nov 2025 | | |

1 1

1 1

1

1 1

2

1

1

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

Head lights

Tail lights Indicators Requires Attention

N/A

6.0 mm 6.0 mm 4.0 mm 4.0 mm

| | 11000 | Raci | ic Condition Guide | Report ID: | 27,168,751 | Ve | rsion: |
|--|--|-------------------------|--------------------------------------|---------------------------|--|----------|--------|
| | ntuet | S Dasi | | Created: | 20 Nov 2025 | | |
| | | | Tre | | | | Regi |
| Make: | Toyota | Model: | Hiace | | | ОК | Atte |
| Body Style: | Van | Year: | 2017 | Engine | | | |
| Rego No.: | KUY209 | Rego Expiry: | 28 Oct 2025 | Oil level | | / | |
| WoF Expiry: | 27 Nov 2026 | Odometer: | 151,658 Kms | Smoke & fu | umes | ' | |
| Good No.: | 27168751 | VIN: | JTFHT02P100233543 | Engine per | formance | / | |
| Next Service: | 160,000km | Service History: | Yes | Noise | | V | |
| Note: This report is | • | e for age and mileage D | arts have not been dismantled or | Coolant co | ndition | ' | |
| diagnostic testing u | ndertaken. The vehicle has beection prior to purchase an | een driven up to 50km/ | h from cold. The Vendor recommends a | Cooling pe | erformance | ~ | |
| Key | | | | Radiator / Hoses (visual) | | V | |
| • | t = Rust C = C | Crack *= Deca | lls W = Significant scuffs | Transmiss | ion | | |
| D = Dent $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$ | | | | Operation | | ' | |
| SC W SDW DW W DSCW | | | Noise | | / | | |
| | | | VV D3CVV | Clutch | | | |
| | | | SW | CV joints | | | |
| | TA UT | | | Wheel bea | rings | / | |
| SDW | | | | | | | |
| | IMP II | | sc | Performan | ce | ' | |
| | | | | Hand brak | e | ' | |
| S D SC | | | | | Tyres (lowest observed tread depth of ty | | tyres) |
| | | | | Left front | | | |
| | | | RW | Right front | : | | |
| | \angle | | | Left rear | | | |
| | | | | Right rear | | | |
| Note: some defects and blemishes may not be displayed in the diagram | | | | Spare | | Yes | |
| Body Inspect | ion Comments | | | Suspensio | on | | |
| | | | | Suspension | n performance | / | |
| | | | | Steering p | erformance | ~ | |
| | | | | Shock abso | orbers | ~ | |
| Conditions During Body Inspection Dry | | | Air Condit | ioning / Heater | , | | |
| Under Carriage and Under Bonnet Inspection Comments | | | Operation | | / | | |

| Conditions During Body Inspection | Dry | | | | |
|---|-----|--|--|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | | | |
| Rear wheel drive | | | | | |
| | | | | | |

| Interior Comm | Interior Comments | | |
|------------------|-------------------|--|--|
| Seats: | Good | | |
| Carpets: | Average | | |
| Panels: | Average | | |
| Dashboard: | Good | | |
| General Comments | | | |

| Road Conditions During Test Drive | | Dry | | |
|-----------------------------------|-------------|--------------|----|-------------|
| Engine Timing Mechanism | | Cambelt | | |
| Evidence of Cam Belt Replacement | | ✓ Yes | No | 151,650 Kms |
| Inspected by: | Rowan Fey | | | |
| Published by: | Admond Chan | | | |
| Inspection Date: | 20 Nov 2025 | | | |

| SIGNATURE | | |
|-----------|--|--|

I have read and understood this condition guide:

| NAME | | |
|------|--|--|
| | | |