

•	Report ID:	27,169,938	Version:	1
	Created:	14 Nov 2025		

OK

1

1

1

Requires Attention

N/A

		Doo:	o Condition Cuido	Report ID:	27,169,9
	uner	S Basi	c Condition Guide	Created:	14 Nov 2
Make:	Holden	Model:	Commodore		
Body Style:	Sedan	Year:	2013	Engine	
Rego No.:	RKS438	Rego Expiry:	21 Aug 2026	Oil level	
WoF Expiry:	25 Nov 2026	Odometer:	121,479 Kms	Smoke & fu	ımes
Good No.:	27169938	VIN:	6G1EK5E37CL717946		
Next Service:	135000	Service History:	Yes	Engine performance Noise	
Note: This report is	not a warranty	•		Coolant co	ndition
diagnostic testing un		een driven up to 50km/ł	arts have not been dismantled or a from cold. The Vendor recommends a		erformance
	ection prior to purchase and	u triis can be arranged i	or an additional charge.	Radiator / I	Hoses (visua
<b>Key</b> S = Scratch R :	= Rust C = C	rack * = Deca	ls W = Significant scuffs	Transmiss	ion
D = Dent $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$				Operation	
				Noise	
			J W	Clutch	
				CV joints	
				Wheel bea	rings
$\bigcup \mathcal{U}$				Brakes	
	M 11 >			Performan	ce
				Hand brake	e
SC	8			Tyres (lowe	est observe
				Left front	
			(Q)	Right front	
	$\angle$ $\overline{}$ $\overline{}$			Left rear	
				Right rear	
Note: some defects a	and blemishes may not be	displayed in the diagra	m	Spare	
Body Inspection	on Comments			Suspensio	n

Body	Inspection	on Comr	ments
------	------------	---------	-------

Rear tint damage

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Greg Morgan	
Published by:	Luke Kerr	
Inspection Date:	04 Nov 2025	

I have read and understood	
this condition guide:	NAME

Cooling performance			
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	<b>/</b>		
Noise	<b>/</b>		
Clutch			<b>'</b>
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		7	7.0 mm
Right front		7	7.0 mm
Left rear		7	7.0 mm
Right rear		7	7.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	<i>'</i>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	<b>/</b>		
Tail lights	<b>V</b>		
Indicators			
Dashboard warning lights	<b>V</b>		
Wipers (front & rear)	<b>/</b>		
Window winder FL	/		
Window winder FR	<b>/</b>		
Window winder RL	<b>/</b>		
Window winder RR	<b>/</b>		
Rear view mirrors	/		
Radio (basic test only)	<b>/</b>		
CD (basic test only)			/
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			V
Reversing camera	1		

SIGNATURE			