

## **Basic Condition Guide**

Report ID:	27,170,902	Version:	3
Created:	17 Nov 2025		

Make:	Cubaru	Model:	Caracter	
	Subaru		Forester	
		Year:	2016	Engine
Rego No.:	24 Nov 2026	Rego Expiry: Odometer:	05 Feb 2026	Oil level
WoF Expiry:			93,267 Kms JF2SJ9KC5GG079274	Smoke & fume
Good No.:	27170902	VIN:	No	Engine perfor
Next Service:	103, 272 Kms	Service History:	INO	Noise
Note: This report is This report is a guide	Coolant condi			
liagnostic testing un ull mechanical inspe	dertaken. The vehicle has b ection prior to purchase an	een driven up to 50km/l d this can be arranged f	n from cold. The Vendor recommends a or an additional charge.	Cooling perfo
(ey		,		Radiator / Hos
	= Rust $C = C$	rack *= Deca	ls W = Significant scuffs	Transmission
D = Dent PT	= Paint defect $P = P$	in dent SC = Sto	ne Chips	Operation
sc		SCP	DSC	Noise
				Clutch
	(M)-		S SC	CV joints
0.00				Wheel bearing
S SC				Brakes
	Mr II		SC	Performance
			SC	Hand brake
SC	8			Tyres (lowest
				Left front
			SC	Right front
				Left rear
P(	Right rear			
lote: some defects a	and blemishes may not be	displayed in the diagra	ım	Spare
Body Inspection	Suspension			
Towbar tongue	in boot.			Suspension pe
				Steering perfo
				Shock absorbe
Conditions Dur	ing Body Inspection		Dry	Air Condition
Under Carriage and Under Bonnet Inspection Comments				Operation
				Electrical / Ac
				Head lights
				Tail lights
Interior Comm	ients			Indicators
Seats:	Good			Dashboard wa
Carpets:	Good			Wipers (front 8
Panels:				
Dashboard:	Window wind			
General Comn	Window wind			
				Window wind
				Rear view miri
				Radio (basic te
Road Condition	CD (basic test			
Road Conditions During Test Drive Dry Engine Timing Mechanism Timing Chain				Number of key
	m Belt Replacement	Yes	No Kms	Central locking
LVIGCTICE OF Cal	beit neplacement	L   L   L	140 KIIIS	CCITCIALIOCKIII

	ОК	Requires Attention	N/A
Engine	OK	Attention	14/74
Oil level	<b>V</b>		
Smoke & fumes	<b>/</b>		
Engine performance	<b>/</b>		
Noise	✓ ✓		
Coolant condition	~		
Cooling performance	<b>/</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	<b>V</b>		
Noise	<b>V</b>		
Clutch			<b>V</b>
CV joints	<b>V</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread de	epth of	tyres)	
Left front		3	3.5 mm
Right front			1.5 mm
Left rear		5	5.0 mm
Right rear		5	5.0 mm
Spare	Yes		
Suspension			
Suspension performance	<b>✓</b>		
Steering performance	<b>/</b>		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	<b>/</b>		
Tail lights	<b>/</b>		
Indicators	<b>/</b>		
Dashboard warning lights	<b>/</b>		
Wipers (front & rear)	<b>/</b>		
Window winder FL	/		
Window winder FR	<b>/</b>		
Window winder RL	<b>/</b>		
Window winder RR	<b>✓</b>		
Rear view mirrors	~		
Radio (basic test only)	<b>/</b>		
CD (basic test only)	<b>✓</b>		
Number of keys	1		
Central locking	<b>/</b>		
Remote locking	•		
Sat. nav. (basic test only)	•		
Reversing camera	<b>V</b>		

I have read and understood this condition guide:

Inspection Date: 05 Nov 2025

Inspected by:
Published by:

NAME

Troy Smith

Shanna Bullion

SIGNATURE