

Basic Condition Guide

Report ID: 27,171,219		Version:	1
Created:	11 Nov 2025		


Make:	Subaru	Model:	Outback
Body Style:	suv	Year:	2018
Rego No.:	LGT812	Rego Expiry:	25 Mar 2026
WoF Expiry:	24 Nov 2026	Odometer:	199,745 Kms
Good No.:	27171219	VIN:	JF2BS9KC2HG067866
Next Service:	210,000 Kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle habeen driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

110)				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Seats: Good Carpets: drivers footwell worn otherwise good Papels: Good	Interior Comments			
-	Seats: Good			
Panels: Good	Carpets: drivers footwell worn otherwise good			
raileis.	Panels:	Good		
Dashboard: Good	Dashboard:	Good		

General Comments

Road Conditions During Test Drive		Dry
Engine Timing I	Mechanism	Timing Chain
Evidence of Can	n Belt Replacement	Yes No Kms
Inspected by:	Kyle Kelly	
Published by:	Ryan Stanley	
Inspection Date:	06 Nov 2025	

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\ti}\xi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\xi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\ti}}\\ \tittt{\text{\text{\text{\text{\text{\text{\texi}\tilit{\titt{\text{\tin}\tilit{\text{\text{\text{\texi}\tilit{\text{\tilit{\text{\text{\text{\texi}\tilit{\text{\texi}\til\til\til\til\tittt{\text{\texi{\texi{\texi{\texi{\texi{\texi}\tii}\\ \tittt{\tilitt{\tii}\tiittt{\tiitt{\tii}\tii}\tiitt{\tiitt{\tilit{\		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		3	3.8 mm
Right front			1.4 mm
Left rear			1.4 mm
Right rear		5	5.4 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	/		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)	/		
Reversing camera	/		

I have read and understood this condition guide:

NAME