

Report ID:	27,171,584	Version:	1
Created:	07 Nov 2025		

	11000	Rasi	c Condition Guide	Report ID: 2	7,171,584	Ve	rsion: 1	
	uner	<u> </u>		Created: 0	7 Nov 2025			
Make:	Toyota	Model:	Camry			01/	Requires	
Body Style:	Sedan	Year:	2018	Engine		OK	Attention	N/A
Rego No.:	LCY218	Rego Expiry:	24 Feb 2026			<b>/</b>		
WoF Expiry:	22 Nov 2025	Odometer:	212,114 Kms	Oil level Smoke & fumes		~		
Good No.:	27171584	VIN:	6T1BF3FK00X109468			~		-
Next Service:	216,000	Service History:	No	Engine perfor Noise		<u> </u>		-
Note: This report is	s not a warranty	Coolant cond		~				
his report is a guid	le only. Consideration is ma undertaken. The vehicle ha l			~				
diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling perfo				
Кеу					(1100.0.1)	<u> </u>		
		Crack *= Deca		Transmission Operation		. 1	1	
D = Dent P	P = Dent $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$					<u> </u>		
SC W		SC SC W	SC SC	Noise		<b>✓</b>		
				Clutch				<b>'</b>
			S SC W	CV joints		<u> </u>		
S SC W				Wheel bearin	gs	<b>/</b>		
- P				Brakes			ı	
				Performance		<u> </u>		
				Hand brake		<u> </u>		
sc				Tyres (lowest observed tread depth of tyres)				
				Left front		3.3 mm		
	sc					3.3 mm		
				Left rear				5 mm
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$				Right rear		6 mm		
Note: some defects	s and blemishes may not be	e displayed in the diagra	ım	Spare		Yes		
<b>Body Inspect</b>	ion Comments			Suspension				
				Suspension p	erformance	<b>/</b>		
				Steering perfo	ormance	<b>/</b>		
				Shock absorb	ers	<b>/</b>		
Conditions Du	ıring Body Inspection		Dry	Air Condition	ning / Heater			
Under Carriage and Under Bonnet Inspection Comments			Operation		<b>/</b>			
				Electrical / A	ccessories			
				Head lights		<b>/</b>		
				Tail lights		<b>/</b>		
Interior Comments				Indicators		<b>/</b>		
Seats:			Dashboard w	arning lights	~			
Carpets:	Average		·····	Wipers (front		1		
Panels:	Average			Window wind		<u>'</u>		
. arreis.				TTILIGOV VIIIC		•	-	<del></del>

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Unknown		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Tyler Le Bherz			
Published by:	Tyler Le Bherz			
Inspection Date:	07 Nov 2025			

Average

Dashboard:

**General Comments** 

have read and understood this condition quide:		

Window winder FR

Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1

1 1

2

1

1

NAME SIGNATURE