


# **Basic Condition Guide**

Report ID:	27,171,794	Version:	3
Created:	08 Nov 2025		

Make:	Nissan	Model:	Juke
Body Style:	SUV	Year:	2020
Rego No.:	MYU668	Rego Expiry:	30 Jan 2026
WoF Expiry:	21 Nov 2026	Odometer:	99,238 Kms
Good No.:	27171794	VIN:	SJNFAAF16A1033167
Next Service:	109,000 Kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

**General Comments** 

Conditions During Body Inspection	Dry			
Under Carriage and Under Ronnet Inspection Comments				

Interior Comments		
Seats: drivers seat worn otherwise good		
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

### Road Conditions During Test Drive Dry Timing Chain **Engine Timing Mechanism** Evidence of Cam Belt Replacement No Yes Kms Kyle Kelly Inspected by: Published by: Jayson Rodriguez Inspection Date: 06 Nov 2025

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	<b>/</b>		
Engine performance	\( \text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tinit}\\ \text{\texi{\text{\texi{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}}\\ \tittt{\text{\text{\text{\text{\text{\text{\text{\ti}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tetx{\text{\text{\texi}\titt{\text{\texi}\tittitt{\text{\text{\tex{\texi}\tiliz}{\text{\text{\text{\texi}\tiint{\text{\texi}\tint{\text{\texi}\tilit{\text{\ti}\tiint{\text{\tii}}\tiint		
Noise	<b>/</b>		
Coolant condition	/		
Cooling performance	<b>/</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	<b>/</b>		
Noise	<b>/</b>		
Clutch			1
CV joints	<b>/</b>		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		5	5.9 mm
Right front		6	3.2 mm
Left rear		2	2.9 mm
Right rear		1	1.6 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	<b>✓</b>		
Electrical / Accessories			
Head lights	<b>/</b>		
Tail lights	<b>✓</b>		
Indicators	<b>✓</b>		
Dashboard warning lights	<b>✓</b>		
Wipers (front & rear)	<b>✓</b>		
Window winder FL	<b>/</b>		
Window winder FR	/		
Window winder RL	<b>/</b>		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)			<b>'</b>
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)	/		
Reversing camera	/		

I have read and understood this condition guide:

NAME

SIGNATURE