

| Report ID: | 27,171,804 | Version: | 2 |
|------------|-------------|----------|---|
| Created: | 17 Dec 2025 | | |

| ca T | ntuet | Basi | c Condition Guide | Пероген | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|------------------------------|--------------------------|------------|--|--|
| | oniei | | | Created: | | |
| Make: | Mazda | Model: | Axela | | | |
| Body Style: | Hatchback | Year: | 2015 | Engine | | |
| Rego No.: | | Rego Expiry: | | Oil level | | |
| WoF Expiry: | 19 Nov 2026 | Odometer: | 57,214 Kms | Smoke & | | |
| Good No.: | 27171804 | VIN: | 7AT0C13JX25109667 | | | |
| Next Service: | 67200 kms | Service History: | No | Engine p | | |
| Note: This report is | s not a warranty | | | Coolant | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a | | | | | | |
| | pection prior to purchase an | d this can be arranged f | or an additional charge. | Cooling | | |
| Key $S = Scratch$ R |) Duct C C | rade * Dosa | ls W Ciamificant souffs | Transmi | | |
| | R = Rust $C = CPT = Paint defect$ $P = P$ | | | Operation | | |
| | | | | Noise | | |
| | | | | Clutch | | |
| | | | | CV joints | | |
| | (O) _[| | | Wheel be | | |
| \bigcirc | | | | Brakes | | |
| | 119 | | | Performa | | |
| | | | | Hand bra | | |
| | HR W | | | Tyres (lo | | |
| | | | | Left fron | | |
| | | | (Q) | Right fro | | |
| | | | | Left rear | | |
| | | | | Right rea | | |
| Note: some defects | s and blemishes may not be | displayed in the diagra | am | Spare | | |
| Body Inspect | ion Comments | | | Suspens | | |
| | | | | Suspens | | |
| | | | | Steering | | |
| | | | | Shock ab | | |
| Conditions Du | ring Body Inspection | | Wet | Air Cond | | |
| Under Carria | ge and Under Bonnet | Inspection Comm | nents | Operation | | |
| Front Wheel Di | rive | | | Electrica | | |
| | | | | Head lig | | |
| | | | | Tail light | | |
| Interior Com | ments | | | Indicator | | |
| Seats: | Good | | | Dashboa | | |
| Carpets: | Good | | | Wipers (f | | |
| Panels: | Good | | | Window | | |
| Dashboard: | Good | | | Window | | |
| General Com | ments | | | Window | | |
| <u> </u> | | | | Window | | |
| | | | | Rearview | | |

| | ОК | Requires Attention | N/A |
|----------------------------------------|----------|-----------------------|--------|
| Engine | | Accention | 1477 |
| Oil level | • | | |
| Smoke & fumes | ~ | | |
| Engine performance | / | | |
| Noise | V | | |
| Coolant condition | 1 | | |
| Cooling performance | V | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | l | |
| Operation | 1 | | |
| Noise | 1 | | |
| Clutch | | | - |
| CV joints | 1 | | |
| Wheel bearings | 1 | | |
| Brakes | | <u> </u> | |
| Performance | 1 | | |
| Hand brake | 1 | | |
| Tyres (lowest observed tread d | enth of | tvres) | |
| Left front | Сригог | | 6.0 mm |
| Right front | | | 6.0 mm |
| Left rear | | | 7.0 mm |
| Right rear | | | 7.0 mm |
| Spare | N/A | | |
| Suspension | 14// (| | |
| Suspension performance | / | I | |
| Steering performance | <i>y</i> | | |
| Shock absorbers | <i>y</i> | | |
| Air Conditioning / Heater | | | |
| Operation Operation | 1 | <u> </u> | |
| Electrical / Accessories | | | |
| | ·/ | I | |
| Head lights Tail lights | ~ | | |
| Tail lights Indicators | | | |
| | V | | |
| Dashboard warning lights | V | | |
| Wipers (front & rear) Window winder FL | <i>'</i> | - | |
| Window winder FL Window winder FR | <i>'</i> | - | |
| | <i>'</i> | | |
| Window winder RL | <i>'</i> | | |
| Window winder RR | <i>'</i> | | |
| Rear view mirrors | <i>'</i> | - | |
| Radio (basic test only) | | | |
| CD (basic test only) | 2 | <u> </u> | L |
| Number of keys | 2 | 1 | |
| Central locking | / | | |
| Remote locking | ' | | |
| Sat. nav. (basic test only) | | | |
| Reversing camera | <i>,</i> | <u> </u> | |

I have read and understood this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 02 Dec 2025

Marlon Espena

Jesh Singh

Engine Timing Mechanism

Inspected by:

Published by:

| N | Δ | M | F |
|---|---|---|---|

Wet

Timing Chain

No

Yes

SIGNATURE

Kms