

Basic Condition Guide

Report ID:	27,172,026	Version:	1
Created:	06 Nov 2025		

		ОК	Requires Attention	N/A
	Engine			
	Oil level	/		
LZ001514	Smoke & fumes	/		
	Engine performance	/		
	Noise	/		
dismantled or	Coolant condition	/		
dor recommends a ge.	Cooling performance	/		
	Radiator / Hoses (visual)	/		
ignificant scuffs	Transmission			
	Operation	/		
	Noise	/		
	Clutch			~
SC	CV joints	/		
	Wheel bearings	/		
	Brakes			
	Performance	'		
SC	Hand brake	V		
H.	Tyres (lowest observed tread	depth of	tyres)	
	Left front			3 mm
	Right front			4 mm
	Left rear			5 mm
	Right rear			5 mm
	Spare	Yes		
	Suspension			
	Suspension performance	V		
	Steering performance	1		
	Shock absorbers	1		
	Air Conditioning / Heater			
	Operation	V		
	Electrical / Accessories			
	Head lights	V		
	Tail lights	1		
	Indicators	1		
	Dashboard warning lights	1		
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	Wipers (front & rear) Window winder FL	V		
		1		
	Window winder FR	<i>\</i>		
	Window winder RL	V		
	Window winder RR	/		
	Rear view mirrors	/		
	Radio (basic test only)	/		
	CD (basic test only)			
	Number of keys	1		1
Kms	Central locking	'		
	Remote locking	'		
	Sat. nav. (basic test only)	'	ļ	
	Reversing camera	V		


Make:	Mitsubishi	Model:	Outlander
Body Style:	SUV	Year:	2021
Rego No.:	NSD7	Rego Expiry:	22 Aug 2026
WoF Expiry:	17 Sep 2026	Odometer:	47,268 Kms
Good No.:	27172026	VIN:	JMFXLGF6WLZ001514
Next Service:	52,000km	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Roof Rack key missing.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		
Under Carriage and Under Bonnet Inspection Comm	ents	

Interior Comments	
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

4WD.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Car	n Belt Replacement	Yes No Kms
Inspected by:	Sharnae Smith	
Published by:	Sharnae Smith	
Inspection Date:	06 Nov 2025	

I have read and understood this condition guide:

NAME SIGNATURE