

Basic Condition Guide

Report ID:	27,172,673	Version:	2
Created:	20 Nov 2025		

	ome	S Das		Created:	20 Nov 2025			
Make:	Ssangyong	Model:	Korando				Requires	
Body Style:	SUV	Year:	2014			OK	Attention	N/A
Rego No.:	NDE171	Rego Expiry:	18 Apr 2026	Engine		1		
	- 55 γ γ γ ·			Oil level				
			KPTB0A18SEP171708	Smoke & fumes				<u> </u>
Good No.: 27172673 VIN: KPTB0A18SEP171708 Next Service: 144690 Service History: No					Engine performance			<u> </u>
		Noise		/				
Note: This report is This report is a guide	only. Consideration is mad	e for age and mileage. P	Coolant condition		/		<u> </u>	
diagnostic testing ur full mechanical insp	ndertaken. The vehicle has b ection prior to purchase an	oeen driven up to 50km/ nd this can be arranged f	Cooling performance		/			
Key				Radiator / Hoses (visual)				
-	= Rust $C=C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion			
D = Dent $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$				Operation 🗸			<u> </u>	
S		SP SP	S	Noise		~		
	$\overline{}$		Clutch		1			
	(M)-		CV joints			'		
S SC			Wheel bearings 🗸					
-330 A				Brakes				
			S	Performan	ce	/		
				Hand brak	e	/		
S P SC				Tyres (lowest observed tread depth of tyres)				
				Left front 6.0 mm				
			S	Right front 6.0 mm				
				Left rear 6.5 mr				
S		S P S P	SP	Right rear 6.5 mm				6.5 mm
Note: some defects	and blemishes may not be	e displayed in the diagr	am	Spare		Yes		
Body Inspecti	on Comments			Suspensio	n		_	
				Suspension	n performance	/		
				Steering p	erformance	/		
				Shock abso	orbers	/		
Conditions Du	ring Body Inspection		Air Conditioning / Heater					
Under Carriag	je and Under Bonnet	t Inspection Comn	Operation		/			
				Electrical	Accessories		_	
				Head light	5	/		
				Tail lights		/		
Interior Comn	nents			Indicators		~		
Seats:	drivers seat rippe	d		Dashboard	l warning lights	/		
Carpets:	Average			Wipers (fro	nt & rear)	1		
Panels: Average				Window w	inder FL	1		
Dashboard:	Average		Window w	inder FR	1			
General Comr	ments	Window w	inder RL	1				
				Window w	inder RR	1		
				Rear view i	mirrors	1		
				Radio (bas	c test only)	1		
Road Condition	ns During Test Drive	Dry	CD (basic test only)				1	
Engine Timing Mechanism Timing Chain					keys	1		
Evidence of Cam Belt Replacement Yes No Kms				Central loc	king	1		
Inspected by: Samuel Weir			Remote lo		1			
							 	\vdash

I have read and understood this condition guide:

Inspection Date: 12 Nov 2025

Published by:

NAME

James Scott

SIGNATURE

Sat. nav. (basic test only)

Reversing camera