

•	Report ID:	Report ID: 27,174,854		4
	Created:	13 Nov 2025		

T	urner	S Basi	c Condition Guide	Created: 13 Nov 202		rsion: 4		
Make:	Holden	Model:	Captiva 5			Requires		
Body Style:	SUV	Year:	2014		OK	Attention	N/A	
Rego No.:	HPL214	Rego Expiry:	02 Aug 2026	Engine				
WoF Expiry:	30 Sep 2026	Odometer:	275,284 Kms	Oil level				
Good No.:	27174854	VIN:	KL3DA26U9EB023161	Smoke & fumes	/			
			Yes	Engine performance	/			
Next Service: 280,000 Service History: Yes  Note: This report is not a warranty				Noise				
his report is a guid	le only. Consideration is mad	e for age and mileage. Pa	arts have not been dismantled or	Coolant condition				
	ındertaken. The vehicle has b pection prior to purchase an		h from cold. The Vendor recommends a or an additional charge.	Cooling performance	/			
Zey				Radiator / Hoses (visual)	<b>/</b>			
-	R = Rust $C = C$	Crack *= Deca	ls W = Significant scuffs	Transmission				
D = Dent	PT = Paint defect P = P	in dent SC = Sto	ne Chips	Operation	<b>/</b>			
		D		Noise	<b>/</b>			
				Clutch			/	
				CV joints	V			
0.00	MA UN			Wheel bearings	/			
s sc				Brakes				
				Performance	· ·			
				Hand brake	V			
P SC	18			Tyres (lowest observed tread depth of tyres)				
S R SC PT				Left front		4.0 mm		
				Right front		4.0 mn		
				Left rear		7.0 m		
		D	D	Right rear		7.0 m		
lote: some defect	s and blemishes may not be	e displayed in the diagra	am	Spare	Yes	Yes		
	tion Comments			Suspension				
Headlights fac	led. Poor repair on tail	gate, paint has crac	king	Suspension performance	· /			
				Steering performance	· ·			
				Shock absorbers	V			
Conditions Du	uring Body Inspection		Dry	Air Conditioning / Heate	er			
	ge and Under Bonnet	Inspection Comm	nents	Operation		V		
		. •		Electrical / Accessories				
				Head lights	· /			
				Tail lights	1			
Interior Comments				Indicators	· ·			
Seats:	Average			Dashboard warning lights				
Carpets:	Average		Wipers (front & rear)	· ·				
Panels: Average			Window winder FL	V	+			
Dashboard:				Window winder FR		+	<del>                                     </del>	
General Comments						-		
Air conditioning noisy when on				Window winder RL	-		-	
				Window winder RR	•	-	-	
				Rear view mirrors	<b>/</b>			

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Cha	ain	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Gary Adams			
Published by:	Anna Zandstra			
Inspection Date:	07 Nov 2025			

I have read and understood this condition guide:

NAME			

SIGNATURE		

1

1 2

•

1

Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera