

## **Basic Condition Guide**

Report ID:	27,175,157	Version:	2	
Created:	28 Nov 2025			

	Ulle			Created:	28 Nov 2025					
Make:	Mitsubishi Model: Eclipse Cross					Requires				
Body Style:	SUV	Year:	2022			OK	Attention	N/A		
Rego No.:	, <u> </u>			Engine				ı		
WoF Expiry:	01 Nov 2026	Odometer:	40,695 Kms	_ Oil level		_				
Good No.:	27175157	VIN:	JMFXDGL3WNZ004700	_ Smoke & f		<b>/</b>				
Next Service:	55000	Service History:	Yes			_				
Note: This report is		Jervice i iistory.	_ Noise		<b>/</b>					
This report is a quide	e only. Consideration is mandertaken. The vehicle has	ade for age and mileage. I	Coolant co		<b>/</b>					
full mechanical insp	pection prior to purchase a	and this can be arranged		cironnance	<b>/</b>					
Key			'	Radiator /	Hoses (visual)					
S = Scratch R	= Rust C =	Crack *= Dec	als W = Significant scuffs	Transmis	Transmission					
D = Dent $PT$ = Paint defect $P$ = Pin dent $SC$ = Stone Chips						<b>/</b>				
		SP		Noise		<b>/</b>				
		$\top$		Clutch				~		
	( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )			CV joints		<b>/</b>				
	MA U			Wheel be	arings	<b>/</b>				
				Brakes	Brakes					
	IMF 11			Performa	nce	<b>/</b>				
				Hand bral	ke e	<b>/</b>				
	18			Tyres (low	Tyres (lowest observed tread depth of tyres)					
				Left front		5.0 mm				
			(Q)	Right fron	t	5.0 mm				
				Left rear		5.0 mm				
		][		Right rear	,	5.0 mm				
Note: some defects	and blemishes may not I	be displayed in the diagi	ram	Spare	I	N/A				
Body Inspecti	ion Comments			Suspensi	on					
				Suspensio	on performance	/				
				Steering p	performance	/				
				Shock abs	sorbers	/				
Conditions Du	ring Body Inspection	1		Air Condi	Air Conditioning / Heater					
Under Carriag	ge and Under Bonne	et Inspection Comr	Operation		/					
				Electrical	/ Accessories					
				Head ligh	ts	/				
				Tail lights		/				
Interior Comn	ments			Indicators	,	/				
Seats:	Good			Dashboar	d warning lights	/				
Carpets:	Good			_		/				
Panels:	Good			- Window v		/				
Dashboard:	Good			Window v		/				
General Com			Window		/					
	and Commercial cha	arging cables suppli	Window		/					
		3 3		Rear view		_				
						_				
Road Condition	ns During Test Drive	Dry	CD (basic	,	-		·			
Engine Timing		Timing Chain	Number o		 2					
			_	-7-	<u> </u>					
Evidence of Cam Belt Replacement Yes No Kms  Inspected by: Kilipati Mae					_	<b>/</b>				
inspected by:	I KIIIDAU IVIAE			Remote lo	ocking	v i		I		

I have read and understood this condition guide:

Inspection Date: 10 Nov 2025

**Bruce Screaton** 

Published by:

NAME \_\_\_\_\_

SIGNATURE

Sat. nav. (basic test only)

Reversing camera