

| • | Report ID: | 27,176,276 | Version: | 1 |
|---|------------|-------------|----------|---|
| | Created: | 12 Nov 2025 | | |


| Make: | Mazda | Model: | CX-5 |
|---------------|-------------|------------------|-------------------|
| Body Style: | Wagon | Year: | 2015 |
| Rego No.: | NMJ55 | Rego Expiry: | 02 Dec 2025 |
| WoF Expiry: | 07 Jul 2026 | Odometer: | 154,868 Kms |
| Good No.: | 27176276 | VIN: | 7AT0C144X20118615 |
| Next Service: | 163,000 | Service History: | Yes |

| Note: This re | nort is not | a warranty |
|---------------|-------------|------------|
| | | |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsS = ScratchW = Significant scuffs R = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Tire inflation device in the boot. Stone chips and scratches all over

| Conditions During Body Inspection | Dry | | |
|---|-----|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | |

| Interior Comments | | |
|-------------------|---------|--|
| Seats: | Average | |
| Carpets: | Average | |
| Panels: | Average | |
| Dashboard: | Average | |

General Comments

1 remote nw. Air conditioning and heating systems along with reverse camera ok

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|--------------------|--------------|
| Engine Timing I | Mechanism | Timing Chain |
| Evidence of Can | n Belt Replacement | Yes No Kms |
| Inspected by: | Gary Adams | |
| Published by: | Bevan Hogg | |
| Inspection Date: | 11 Nov 2025 | |

| | ОК | Requires Attention | N/A |
|--------------------------------|-------------|-----------------------|----------|
| Engine | OK | Attention | IN/A |
| Oil level | V | | <u> </u> |
| Smoke & fumes | ~ | | |
| Engine performance | | | |
| Noise | V | | |
| Coolant condition | ~ | | |
| | ~ | | |
| Cooling performance | <i>'</i> | | |
| Radiator / Hoses (visual) | | | |
| Transmission | | <u> </u> | l |
| Operation | | | |
| Noise | - | | |
| Clutch | _ | | |
| CV joints | • | | |
| Wheel bearings | | | |
| Brakes | _ | I | |
| Performance | / | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 3 | 3.0 mm |
| Right front | | 3 | 3.0 mm |
| Left rear | | | 5.0 mm |
| Right rear | | | 1.0 mm |
| Spare | N/A | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | 1 | | |
| Electrical / Accessories | | | |
| Head lights | 1 | | |
| Tail lights | V | | |
| Indicators | / | | |
| Dashboard warning lights | 1 | | |
| Wipers (front & rear) | 1 | | |
| Window winder FL | 1 | | |
| Window winder FR | 1 | | |
| Window winder RL | 1 | | |
| Window winder RR | | | |
| Rear view mirrors | V | | |
| Radio (basic test only) | 1 | | |
| CD (basic test only) | 1 | | |
| Number of keys | 2 | <u> </u> | |
| Central locking | _ | | |
| Remote locking | <i>\'\'</i> | | |
| Sat. nav. (basic test only) | _ | | 1 |
| Reversing camera | V | | <u> </u> |
| neversing current | _ | | |

I have read and understood this condition guide: