

•	Report ID:	27,177,362	Version:	1	
	Created:	13 Nov 2025			

N/A

3.0 mm 2.5 mm 7.0 mm 6.5 mm

1

1

1

1

		Posi	c Condition Guide	Report ID:	27,177,362	Ve	rsion:	1
	nuer	<u> </u>	C Condition Guide	Created:	13 Nov 2025			
Make:	Mazda	Model:	Axela				Requi	ires
Body Style:	Sedan	Year:	2008			OK	Atten	
Rego No.:	HEW365	Rego Expiry:	05 Jan 2026	Engine				
	13 May 2026	Odometer:	195,984 Kms	Oil level		/		
WoF Expiry: Good No.:	27177362	VIN:	7AT0C13JX13313242	Smoke & fu	imes	/		
			No	Engine per	formance	/		
Next Service:	195000	Service History:	INO	Noise		1		
Note: This report is This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant condition		<b>/</b>		
diagnostic testing ur	ndertaken. The vehicle has b ection prior to purchase and	een driven up to 50km/ł	n from cold. The Vendor recommends a	Cooling pe	rformance	/		
Key				Radiator / H	Hoses (visual)	<b>/</b>		
-	= Rust C = C	rack * = Deca	ls W = Significant scuffs	Transmissi	ion			
D = Dent P	T = Paint defect P = Pi	in dent SC = Stor	ne Chips	Operation		<b>/</b>		
S	6.0	PTPSDPTP	SPTP	Noise		<b>'</b>		
ر می از		JETE	3FIF	Clutch				
			SPW	CV joints		~		
	MA UT			Wheel bea	rings	1		
SPTCW				Brakes				
	M 11.			Performan	ce	1		
			SDPT	Hand brake	2	1		
SDPSCW	18			Tyres (lowest observed tread depth of tyres)				
				Left front				3.
			SDP	Right front				2.
				Left rear				7.
SDP		SP SDP	SPW	Right rear				6.
Note: some defects	and blemishes may not be	displayed in the diagra	ım	Spare		Yes		
	on Comments			Suspensio	n			
Drivers Door - 0	Cannot Control Rear V	Vindows		Suspension	n performance	V		П
Water in Boot				Steering pe		1		
Boot Struts Not	Working			Shock abso		1		
Conditions Du	ring Body Inspection		Dry		ioning / Heater			
	e and Under Bonnet	Inspection Comm	•	Operation	<u> </u>		·	. [
Oil Leak	,				'Accessories			
				Head lights		V	Ĭ	Ī
				Tail lights		1		$\dashv$
Interior Comn	nents			Indicators		1	<del>                                     </del>	$\dashv$
Seats:	Average				warning lights	1		-+
Carpets:	Average			Wipers (fro		1		-
Panels:	Average			Window w		1	-	-+
i di icis.	Average			VVIII IUUVV VV	IIIGEI I L	_	1	- 1

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

## Rear Suspension Harsh

Road Conditions During Test Drive		Dry		
Engine Timing I	Mechanism	Timing Cha	in	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Darren Beban			
Published by:	James Scott			
Inspection Date:	13 Nov 2025			

I have read and understood
this condition guide:

NAME			

SIGNATURE		

Window winder FR Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking