

Basic Condition Guide


| Report ID: | 27,177,391 | Version: | 1 |
|------------|-------------|----------|---|
| Created: | 10 Nov 2025 | | |

| Make: | Mazda | Model: | Mazda3 |
|---------------|-------------|------------------|-------------------|
| Body Style: | Hatchback | Year: | 2021 |
| Rego No.: | NTZ176 | Rego Expiry: | 21 Jan 2026 |
| WoF Expiry: | 20 Oct 2026 | Odometer: | 76,258 Kms |
| Good No.: | 27177391 | VIN: | JM0BP2H7A01141154 |
| Next Service: | 90291 | Service History: | Yes |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

| Interior Comments | | |
|-------------------|------|--|
| Seats: | Good | |
| Carpets: | Good | |
| Panels: | Good | |
| Dashboard: | Good | |
| General Comments | | |

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|--------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Kilipati Mae | |
| Published by: | Kilipati Mae | |

| | ОК | Requires Attention | N/A |
|---------------------------------|---------------------------------------|-----------------------|----------|
| Engine | | | |
| Oil level | / | | |
| Smoke & fumes | / | | |
| Engine performance | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Noise | / | | |
| Coolant condition | / | | |
| Cooling performance | / | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | / |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand brake | / | | |
| Tyres (lowest observed tread de | pth of | tyres) | |
| Left front | | | 7 mm |
| Right front | | | 7 mm |
| Left rear | | | 7 mm |
| Right rear | | | 7 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | / | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | / | | |
| Indicators | / | | |
| Dashboard warning lights | / | | |
| Wipers (front & rear) | / | | |
| Window winder FL | • | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | / | | |
| Rear view mirrors | / | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | | | / |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | • | | |
| Reversing camera | / | | |

I have read and understood this condition guide:

Inspection Date: 10 Nov 2025

NAME

SIGNATURE