

Report ID: 27		27,178,965	Version:	1
	Created:	11 Nov 2025		

Basic Condition Guide		Report ID: 27,178,965 Version: 1						
	ullei	<u> </u>		Created:	11 Nov 2025			
Make:	Mini	Model:	ONE				Requires	
Body Style:	Hatchback	Year:	2012	Engine		OK	Attention	N/A
Rego No.:	GLK118	Rego Expiry:	01 Feb 2026	Engine		V		
WoF Expiry:	08 Aug 2026	Odometer:	63,874 Kms	Oil level		1		-
Good No.:	27178965	VIN:	WMWSR32040TY61450	Smoke & fumes		V		-
Next Service:	71267	Service History:	Yes	Engine performance Noise		V		-
lote: This report is	not a warranty	'	112122		1			
his report is a guido iagnostic testing u	e only. Consideration is mad ndertaken. The vehicle ha b	de for age and mileage. I been driven up to 50km/	Cooling performance		V			
	ection prior to purchase an				V			
(ey			ls W = Significant scuffs	Transmiss	Hoses (visual)		<u> </u>	
	= Rust C = C			ion	V	<u> </u>		
D = Dent P	T = Paint defect P = P	Pin dent SC = Sto	ne Cnips	Operation		1		-
s sc	5	SSC	SSC	Noise		-		
			Clutch		1		-	
	\sim		S SC	CV joints Wheel bea	win an	1		-
s sc			Brakes	rings				
$\overline{}$	MATT		THE REPORT OF THE PERSON OF TH	Performan		V		
1				Hand brake		1		-
222	HO !!			Traile State				
s sc			Tyres (lowest observed tread depth of tyres) Left front 5 mm					
		+	Right front				5 mr	
			Left rear	•			5 mi	
S SC	W	SSC					5 mi	
			Right rear		N/A		3 1111	
	and blemishes may not be on Comments	e displayed in the diagra	Spare N/A Suspension					
Boot button wo				-		V	Ī	
Door Dation Wo	111/			•	n performance erformance	V		
				Shock abso		V		
Conditions Du	ring Body Inspection		Dry		ioning / Heater		l	
	ge and Under Bonnet	t Inspection Comm		ioning / Heater	V			
	ne oil leak further inve		Operation Electrical / Accessories					
zwa/major engi	no on loak farther live	ooligation needed/				V		
				Head lights Tail lights	5	V		\vdash
Interior Comments						V		\vdash
				Indicators	l warning lights	V		
	Average		Wipers (fro		V		<u> </u>	
Carpets: Panels:	Average		Window w		V		<u> </u>	
0					1		<u> </u>	
Dashboard:	Average			Window w		-		
General Com	ments			Window w	inder KL			

I have read and	understood thi	is condition quide:
Thave read and	unucistodu tin	is contantion quide.

Uriah Pepene

Uriah Pepene

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 11 Nov 2025

Engine Timing Mechanism

Inspected by:

Published by:

Dry

Timing Chain

No

Yes

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

1

1

1

1

1