

Basic Condition Guide

Report ID:	27,179,285	Version:	4
Created:	18 Nov 2025		

	Dillei	<u> </u>		Created:			
Make:	Nissan	Model:	Navara				
Body Style:	Utility	Year:	2011	Engine			
Rego No.: GCG387		Rego Expiry:	09 Sep 2026	Oil level			
WoF Expiry:	26 Nov 2026	Odometer:	268,150 Kms	Smoke & fr			
Good No.:	27179285	VIN:	VSKCVND40A0433492	Engine per			
Next Service:	276,000	Service History:	Yes	Noise			
Note: This report is	•			Coolant co			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							
	ection prior to purchase an	d this can be arranged fo	or an additional charge.	Cooling pe			
Key	= Rust C = C	rack *= Deca	W Cignificant couffs	Transmiss			
	= Rust C = C T = Paint defect P = Pi			Operation			
				Noise			
	P	sc sc	W SC	Clutch			
				CV joints			
			SP	Wheel bea			
w sc				Brakes			
	19/1/1			Performan			
			SC	Hand brak			
SC	18 VI			Tyres (low			
				Left front			
			(Q) WD	Right front			
				Left rear			
		S P S P	W SC	Right rear			
Note: some defects and blemishes may not be displayed in the diagram							
Body Inspecti	on Comments			Suspensio			
				Suspensio			
				Steering p			
				Shock abs			
Conditions Du	ring Body Inspection		Dry	Air Condi			
Under Carriag	je and Under Bonnet	Inspection Comm	ents	Operation			
				Electrical			
				Head light			
				Tail lights			
Interior Comn	nents			Indicators			
Seats:	Drivers side worn			Dashboard			
Carpets:	Average			Wipers (fro			
Panels:	Average			Window w			
Dashboard:	Average			Window w			
General Comments							
				Window w			
				Rear view			
				Radio (bas			
Road Condition	ns During Test Drive	Dry		CD (basic t			

		Requires	
	OK	Attention	N/A
Engine			
Oil level			
Smoke & fumes	/		
Engine performance	/		
Noise	✓		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission		Г	
Operation	/		
Noise	/		
Clutch			'
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	✓		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			6.0 mm
Right front			3.0 mm
Left rear			6.0 mm
Right rear		(6.0 mm
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	✓		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	V		
Window winder FR			
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	1		
	-		

I have read and understood this condition guide:

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 12 Nov 2025

Gary Adams

Luke Saunders

NAME

Timing Chain

No

Yes

SIGNATURE

Kms