

Basic Condition Guide


Report ID:	27,179,919	Version:	1
Created:	18 Nov 2025		

	OK	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	1		
Engine performance	V V		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission		ı	
Operation	V		
Noise	1		
Clutch			~
CV joints	1		
Wheel bearings	1		
Brakes	-		
Performance	V		
Hand brake	1		
Tyres (lowest observed tread of	depth of	tyres)	
Left front		3	3.1 mm
Right front		3	3.8 mm
Left rear		2	2.9 mm
Right rear		3	3.6 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	'		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	V		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	~		
Radio (basic test only)	'		
CD (basic test only)	/		
Number of keys	2		
Central locking	~		
Remote locking	V		
Sat. nav. (basic test only)			~
Reversing camera	1		

Make:	Ford	Model:	Territory		
Body Style:	suv	Year:	2014		
Rego No.:	PKQ850	Rego Expiry:	28 Mar 2026		
WoF Expiry:	02 Dec 2026	Odometer:	134,694 Kms		
Good No.:	27179919	VIN:	6FPAAAJGATDE53631		
Next Service:	144600	Service History:	Yes		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					
Key					

\mathbf{v}	~~.
n	eν

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Large dent on boot lid

Left rear tyre starting to wear on outer edge

Conditions During Body Inspection	Wet			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments			
Seats:	Seats: Slight wear on drivers seat		
Carpets: Good			
Panels: Good			
Dashboard:	Good		
General Comments			

Partial service history

Road Conditions During Test Drive Wet Cambelt Engine Timing Mechanism **√** No Evidence of Cam Belt Replacement Yes Kms Hoani Saunders Inspected by: Published by: Malcolm Thomas Inspection Date: 11 Nov 2025

l have	read	and	unde	rstood
this co	nditi	on a	uide	

NAME			