

•	Report ID:	27,179,957	Version:	4
	Created:	25 Nov 2025		

CA T	nuel	S Basi	c Condition Guide	Created:	27,179,957 25 Nov 2025	Ve	rsion: 4	
Make:	Mitsubishi	Model:	Triton			ОК	Requires Attention	N/A
Body Style: Utility Year:		2022	Engine		7100011	14,71		
Rego No.:	NWN661	Rego Expiry:	13 Jun 2026	Oil level		V		
WoF Expiry:	09 Dec 2026	Odometer:	86,605 Kms	Smoke & fu	ımes	1		
Good No.:	27179957	VIN:	MMAJLKL10NH014516	Engine per		1		\vdash
Next Service: 100,000 Service History: Yes			Noise		1		 	
Note: This report is	•			Coolant co	ndition	1		
diagnostic testing ur	ndertaken. The vehicle has b	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling pe		1		\vdash
	ection prior to purchase and	d this can be arranged f	or an additional charge.	- 31	Hoses (visual)	1		
Key		· · · · · · · · · · · · · · · · · · ·	W 6: -: 6: 1 6:	Transmissi				
	= Rust $C = C$ T = Paint defect $P = Pi$		3	Operation 🗸				
	T diffe delect 1		To emps	Noise		1		\vdash
			J W J	Clutch				-
				CV joints		1		+
	$(0)_{\mathbb{Z}}$		(\bigcirc)	Wheel bear	rinas	1		\vdash
W				Brakes	93		l	
M				Performan	ce	V		
]		Hand brake		1		
					Tyres (lowest observed tread depth of tyres)			
$\overline{}$					Left front 9.0 mm			
			(Q)	Right front				9.0 mm
								9.0 mm
PW				Left rear Right rear		9.0 mm		
Note: some defects and blemishes may not be displayed in the diagram				Spare		Yes		
	on Comments	ansprayed in the diagra		Suspensio	n			
				Suspension	n performance	V		
				Steering pe	erformance	1		
				Shock abso	orbers	1		
Conditions During Body Inspection Dry				Air Condit	ioning / Heater		•	
Under Carriage and Under Bonnet Inspection Comments						V		
Vehicle has now been Professionally Treated and Undersealed				Electrical / Accessories				
				Head lights	5	'		
				Tail lights		1		
Interior Comments				Indicators		~		
Seats: Good			Dashboard	l warning lights	1			
Carpets:	Carpets: Good			Wipers (fro	nt & rear)	~		
Panels: Good			Window w	inder FL	1			
Dashboard: Good				Window w	inder FR	~		
	_						t	

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Kilipati Mae	
Published by:	Bruce Screaton	
Inspection Date:	12 Nov 2025	

General Comments

I have read and understood		
this condition quide:	NAME	CICNATURE

Window winder RL Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking •

2

1

•