

## **Basic Condition Guide**

•	Report ID:	27,180,681	Version:	1	
	Created:	17 Nov 2025			

	ntuet	S Dasi	C Condition Guide	Created:	17 Nov 2025				
Make:	Mazda	Model:	Demio				Requires		
Body Style:	Hatchback	Year:	2007	For action a		OK	Attention	N/A	
Rego No.:	LND790	Rego Expiry:	17 Jan 2026	Engine			i	1	
		Odometer:	68,617 Kms	Oil level		<i>\</i>		-	
Good No.:	27180681	80681 VIN: 7AT0C12HX18502372					-		
Next Service:	78596	Service History:	No	Engine performance		<b>/</b>		-	
Note: This report is		Noise		<b>/</b>		-			
Γhis report is a quide	only. Consideration is mad	Coolant co		/		-			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.					rformance	<i>'</i>			
Кеу			Hoses (visual)	/					
S = Scratch R	= Rust $C = C$	Transmission							
D = Dent P	T = Paint defect P = P	Operation		/					
SC		Noise		/					
$\overline{}$	$\overline{}$	Clutch				/			
	\ \(\hat{\omega}_{-}\)		S SC	CV joints		/			
S SC				Wheel bea	rings	<b>/</b>			
330				Brakes					
			sc	Performan	ce	/			
				Hand brak	e	/			
s sc	18			Tyres (lowe	Tyres (lowest observed tread depth of tyres)				
				Left front	Left front 5.8 mm				
			S SC	Right front	Right front 5.8 mm				
				Left rear		4.0 mm			
S SC		Right rear	ht rear 4.3 mm						
Note: some defects	and blemishes may not be	displayed in the diagra	nm	Spare	Spare Yes				
	on Comments			Suspensio	n	-			
, ,				-	n performance	1			
				-	erformance	1			
				Shock abso		1			
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater					
	ge and Under Bonnet	Inspection Comm	Operation		·				
Front wheel driv		, , , , , , , , , , , , , , , , , , ,		•	'Accessories				
				Head light:		V			
				Tail lights	,	1			
Interior Comn	nents			Indicators		· /			
Seats:	Good				l warning lights	V		-	
				Dashboard warning lights Wipers (front & rear)		V		-	
Carpets:	Good			Window w		<i>'</i>		<del>                                     </del>	
						<b>-</b>		<del> </del>	
Dashboard:	Good	Window w		.,	<b>, ,</b>	-			
General Comr				Window w		<b>'</b>		-	
טטנוז ngni side \	windows not working			Window w			<i>'</i>	-	
				Rear view r		<b>/</b>		<u> </u>	
		Dry			c test only)	/		<u> </u>	
	ns During Test Drive	CD (basic t	-			/			
Engine Timing		Number of		2					
Evidence of Cam Belt Replacement Yes No Kms					king	/			
Inspected by:	Cameron Senior-	Arnold		Remote lo	king	/			
	T					I .			

I have read and understood this condition guide:

Inspection Date: 14 Nov 2025

Published by:

NAME

Amanda Mackie

SIGNATURE

Sat. nav. (basic test only)

Reversing camera