

| • | Report ID: 27,180,702 | | Version: | 3 | |
|---|-----------------------|-------------|----------|---|--|
| | Created: | 21 Nov 2025 | | | |

| UT | ntuet | S Basi | c Condition Guide | Created: | 27,180,702 21 Nov 2025 | ve | rsion: 3 | |
|--|--------------------------------------|---------------------------|-----------------------------|--|---------------------------|----------|-----------|----------|
| Make: | Subaru | Model: | Legacy | | | | Requires | |
| Body Style: | Sedan | Year: | 2006 | | | OK | Attention | N/A |
| Rego No.: | DQQ107 | Rego Expiry: | 02 Apr 2026 | Engine | | V | | |
| WoF Expiry: | 28 Nov 2026 | Odometer: | 177,231 Kms | Oil level Smoke & fu | mas | <i>V</i> | | |
| Good No.: | 27180702 | VIN: | 7A8GF0B0706015585 | | | V | | - |
| Next Service: | 187,502km | Service History: | Yes | Engine perf | Tormance | <i>'</i> | | |
| lote: This report is | not a warranty | • | | Coolant cor | ndition | V | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | rformance | V | | <u> </u> |
| | | | | | | V | | |
| (еу | | | | Radiator / Hoses (visual) Transmission | | | | |
| | = Rust $C = CT = Paint defect P = P$ | | 3 | Operation | OII | V | 1 | |
|) – Delit F | T = railit delect F = r | 111 dent 3C = 3tol | ie Chips | - | | V | | |
| SDSC | S | DSC SDSC | SDRW | Noise Clutch | | | | - |
| | | | | | | | | — |
| | \sim | | S D C SC | CV joints Wheel bearings | | | | |
| S SC W | | | | Brakes | | | | |
| M | 10 m | | | Performano | | V | I | |
| | | | S R SC | Hand brake | | V | | \vdash |
| SDSC | 10 | | | Tyres (lowest observed tread depth of tyres) | | | | |
| 0000 | | | | Left front 7.0 mr | | | | |
| S SC | | | | | | 7.0 m | | |
| | | | | Right front Left rear | | 4.0 n | | |
| S D S S D R W Note: some defects and blemishes may not be displayed in the diagram | | | | Right rear | | 4.0 r | | |
| | | | | Spare | | Yes 4.0 | | |
| | ion Comments | e dispiayed in the diagra | III | Suspension | n | | | |
| | | nper poor fit. Minor | stone chips in front screen | • | performance | V | | |
| Ū | | | · | Steering pe | | 1 | | |
| | | | | Shock abso | | 1 | | |
| Conditions During Body Inspection Dry | | | | | Air Conditioning / Heater | | | |
| Under Carriage and Under Bonnet Inspection Comments | | | | | <u> </u> | V | I | |
| • | | • | | Operation Electrical / | Accessories | | | |
| | | | | Head lights | | V | | |
| | | | | Tail lights | | 1 | | |
| Interior Comr | nents | | | Indicators | | 1 | | |
| Seats: Drivers has hole | | | | warning lights | 1 | | | |
| Carpets: Average | | | Wipers (fro | | 1 | | | |
| Panels: Average | | | Window wi | | 1 | | | |
| Dashboard: | cracked | | | Window wi | | 1 | | |
| | | | | | | <u> </u> | 1 | — |

| Carpets: | Average | | |
|--------------|------------------|--|--|
| Panels: | Average | | |
| Dashboard: | cracked | | |
| General Comm | General Comments | | |
| | | | |
| | | | |

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|---------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Gary Adams | |
| Published by: | Anna Zandstra | |
| Inspection Date: | 13 Nov 2025 | |

| l have | read | and | unde | rstood |
|---------|-------|------|------|--------|
| this co | nditi | on a | uide | |

| NAME | | | |
|------|--|--|--|

| SIGNATURE | | | |
|-----------|--|--|--|

1

•

1 1

•

Window winder RL Window winder RR

Rear view mirrors

Number of keys

Central locking Remote locking

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera