

Report ID:	27,181,803	Version:	1
Created:	13 Nov 2025		

U	ntuer	S Basi	C Condition Guide	Created: 13 Nov 202		
Make:	Mazda	Model:	Axela			
Body Style:	Hatchback	Year:	2010	Engine		
Rego No.:	MES317	Rego Expiry:	09 Oct 2025	Oil level		
WoF Expiry:	08 Apr 2026	Odometer:	80,661 Kms	Smoke & fumes		
Good No.:	27181803	VIN:	7AT0C13JX19116389	Engine performance		
Next Service:	90,624kms	Service History:	No	Noise		
Note: This report is	not a warranty			Coolant condition		
diagnostic testing u	e only. Consideration is madendertaken. The vehicle has bection prior to purchase an	een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.	Cooling performance		
<u>.</u>	rection prior to purchase arr			Radiator / Hoses (visual)		
<b>Key</b> $S = Scratch$ R	= Rust	rack * = Deca	ls W = Significant scuffs	Transmission		
	T = Paint defect P = P		•	Operation		
		D D		Noise		
		P P	S P	Clutch		
				CV joints		
	THE WIT			Wheel bearings		
-				Brakes		
	Performance					
				Hand brake		
SC	18			Tyres (lowest observed tr		
			(Q)	Right front		
				Left rear		
		P	S P	Right rear		
Note: some defects	and blemishes may not be	displayed in the diagra	nm	Spare		
Body Inspect	ion Comments			Suspension		
Front parking p	oll broken.			Suspension performance		
				Steering performance		
				Shock absorbers		
Conditions Du	ring Body Inspection		Wet	Air Conditioning / Heate		
Under Carria	Operation					
				Electrical / Accessories		
				Head lights		
				Tail lights		
Interior Com	ments			Indicators		
Seats:	Good			Dashboard warning light		
Carpets:	Good			Wipers (front & rear)		
Panels:				Window winder FL		
Dashboard: Steering wheel worn				Window winder FR		

	ОК	Requires Attention	
Engine	<u> </u>	711111111111111111111111111111111111111	,
Oil level	1		
Smoke & fumes	1		
Engine performance	1		
Noise	/		
Coolant condition	/		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission		1	
Operation	~		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	/		
Brakes	'		
Performance	1		
Hand brake	~		
Tyres (lowest observed tread o	lepth of	tyres)	
Left front		5	5.5 mm
Right front			6 mm
Left rear			1.5 mm
Right rear			5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	<b>V</b>		
Window winder FR			
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	~		
Number of keys	1		
Central locking	<b>'</b>		
Remote locking	<b>'</b>		
Sat. nav. (basic test only)		ļ	
Reversing camera			

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by: LukaAjitvan Woer		den		
Published by: LukaAjitvan Woer		den		
Inspection Date:	13 Nov 2025			

I have read and understood this condition guide:

**General Comments** 

NAME \_

SIGNATURE