

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 27,182,588  | Version: | 1 |
| Created:   | 13 Nov 2025 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Holden      | Model:           | Commodore         |
| Body Style:   | Sedan       | Year:            | 2009              |
| Rego No.:     | FZK361      | Rego Expiry:     | 04 Nov 2025       |
| WoF Expiry:   | 04 Jul 2026 | Odometer:        | 300,000 Kms       |
| Good No.:     | 27182588    | VIN:             | 6G1EP5EY3AL404743 |
| Next Service: | 308,464kms  | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Conditions During Body Inspection Dry

## Under Carriage and Under Bonnet Inspection Comments

L engine mount leak,exhaust bend,underbody rear subframe rust, r front shock leaking, odo 298742

## Interior Comments

|            |         |
|------------|---------|
| Seats:     | Poor    |
| Carpets:   | Poor    |
| Panels:    | Poor    |
| Dashboard: | Average |

## General Comments

Both front seat torn, steering wheel torn, middle console broken,engine light on misfire, air con not cold,rear view mirror faded,driver body seal torn, both front inner guard torn, engine oil leak, R front wheel bend,transmission hose from radiator leak oil,

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Marlon Espena                |                             |     |
| Published by:                     | Marlon Espena                |                             |     |
| Inspection Date:                  | 13 Nov 2025                  |                             |     |

OK Requires Attention N/A

## Engine

|                           |   |   |  |
|---------------------------|---|---|--|
| Oil level                 |   | ✓ |  |
| Smoke & fumes             |   | ✓ |  |
| Engine performance        |   | ✓ |  |
| Noise                     | ✓ |   |  |
| Coolant condition         |   | ✓ |  |
| Cooling performance       |   | ✓ |  |
| Radiator / Hoses (visual) |   | ✓ |  |

## Transmission

|                |   |  |   |
|----------------|---|--|---|
| Operation      | ✓ |  |   |
| Noise          | ✓ |  |   |
| Clutch         |   |  | ✓ |
| CV joints      | ✓ |  |   |
| Wheel bearings | ✓ |  |   |

## Brakes

|             |   |  |  |
|-------------|---|--|--|
| Performance | ✓ |  |  |
| Hand brake  | ✓ |  |  |

## Tyres (lowest observed tread depth of tyres)

|             |      |  |  |
|-------------|------|--|--|
| Left front  | 6 mm |  |  |
| Right front | 6 mm |  |  |
| Left rear   | 3 mm |  |  |
| Right rear  | 3 mm |  |  |
| Spare       | Yes  |  |  |

## Suspension

|                        |   |   |  |
|------------------------|---|---|--|
| Suspension performance | ✓ |   |  |
| Steering performance   | ✓ |   |  |
| Shock absorbers        |   | ✓ |  |

## Air Conditioning / Heater

|           |  |   |  |
|-----------|--|---|--|
| Operation |  | ✓ |  |
|-----------|--|---|--|

## Electrical / Accessories

|                             |   |   |   |
|-----------------------------|---|---|---|
| Head lights                 | ✓ |   |   |
| Tail lights                 | ✓ |   |   |
| Indicators                  | ✓ |   |   |
| Dashboard warning lights    |   | ✓ |   |
| Wipers (front & rear)       | ✓ |   |   |
| Window winder FL            | ✓ |   |   |
| Window winder FR            | ✓ |   |   |
| Window winder RL            | ✓ |   |   |
| Window winder RR            | ✓ |   |   |
| Rear view mirrors           |   | ✓ |   |
| Radio (basic test only)     | ✓ |   |   |
| CD (basic test only)        |   | ✓ |   |
| Number of keys              | 2 |   |   |
| Central locking             | ✓ |   |   |
| Remote locking              | ✓ |   |   |
| Sat. nav. (basic test only) |   |   | ✓ |
| Reversing camera            | ✓ |   |   |

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_