


| • | Report ID: 27,783,908 | | Version: | 1 |
|---|-----------------------|-------------|----------|---|
| | Created: | 27 Nov 2025 | | |

| Peugeot | Model: | 3008 |
|-------------|--|---|
| SUV | Year: | 2018 |
| RAJ334 | Rego Expiry: | 24 Oct 2025 |
| 03 Dec 2026 | Odometer: | 107,336 Kms |
| 27783908 | VIN: | VF3M45GYWHS250552 |
| 117,000 | Service History: | Yes |
| | SUV RAJ334 03 Dec 2026 27783908 | SUV Year: RAJ334 Rego Expiry: 03 Dec 2026 Odometer: 27783908 VIN: |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

| Conditions During Body Inspection | Dry | | | |
|---|-----|--|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | | |

| Interior Comments | | |
|-------------------|---------|--|
| Seats: | Average | |
| Carpets: | Average | |
| Panels: | Average | |
| Dashboard: | Average | |
| General Comments | | |

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|---------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Gary Adams | |
| Published by: | Luke Saunders | |
| Inspection Date: | 14 Nov 2025 | |

| have read and understood | | | |
|--------------------------|------|--|--|
| his condition guide: | NAME | | |

| | OK | Requires Attention | N/A |
|--------------------------------|------------|-----------------------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | / | | |
| Engine performance | 1 | | |
| Noise | / | | |
| Coolant condition | \(\tau \) | | |
| Cooling performance | ~ | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | / |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | / | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 3 | 3.0 mm |
| Right front | | 3 | 3.0 mm |
| Left rear | | 2 | 2.0 mm |
| Right rear | | 3 | 3.0 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | / | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | V | | |
| Dashboard warning lights | | | |
| Wipers (front & rear) | V | | |
| Window winder FL | | | |
| Window winder FR | V | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | 1 | | |
| CD (basic test only) | | | |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | • | | |
| Sat. nav. (basic test only) | • | | |
| Reversing camera | / | | |
| | | <u></u> | |

| SIGNATURE | | |
|-----------|--|--|