

•	Report ID:	27,785,010	Version:	1
	Created:	16 Nov 2025		

UT	ntuet	S Basi	c Condition Guide	Created:	16 Nov 2025	Ve	rsion: 1	
Make:	Daihatsu	Model:	Sirion			01/	Requires	
Body Style:	Hatchback	Year:	2006	Engino		OK	Attention	N/A
Rego No.:	DGC873	Rego Expiry:	31 Dec 2025		V			
WoF Expiry:	08 Oct 2026	Odometer:	80,268 Kms	Oil level Smoke & fumes		1		
Good No.:	27785010	VIN:	JDAM301S001032903	.001032903		1		
Next Service:	Unknown	Service History:	No	Engine performance  Noise		-		
This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or liagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a					ndition	1		
					rformance	1		
ull mechanical inspection prior to purchase and this can be arranged for an additional charge.				31	Hoses (visual)	V		
Key					· · ·			
	= Rust C = C		3	Transmission Operation				
D = Dent P	T = Paint defect P = P	in dent SC = Sto	ne Cnips	Operation		1		-
SDSC	S	S SC S D SC	D SC	Noise		-		1
				Clutch		1		
	(O)E		S SC	CV joints	•	1		
S SC (		<u> </u>		Wheel bear	rings			
-			HIV	Performance				
sc						<i>y</i>		
2222	10< II			Traile brake				
SDSC	S D SC				Tyres (lowest observed tread depth of tyres)  Left front 1.5 mm			
SSC				Left front Right front				
								2 mn
SC								4.5 mn
3C 3 S S S S S S S S S S S S S S S S S S				Right rear				5 mn
	and blemishes may not be	displayed in the diagra	m	Spare		Yes		
	ion Comments			Suspensio			1	
Stonechip/crac Front tyres low	k in windscreen.			-	n performance	/		
Tronk tyroo low	on troad.				erformance	/		
				Shock abso		/		
	ring Body Inspection		Dry		ioning / Heater	_	ı	
Under Carria	ge and Under Bonnet	Inspection Comm	ents	Operation		<b>/</b>		
				Electrical /	Accessories			
				Head lights	5	/		
				Tail lights		/		
Interior Comments				Indicators		<b>/</b>		
Seats: Good			Dashboard	l warning lights	/			
Carpets: Good, missing floor mats.				Wipers (fro	nt & rear)		<b>/</b>	
Panels: Average			Window wi	inder FL	<b>/</b>			
Dashboard: Good				Window wi	inder FR	<b>/</b>		
0.000								

General Comments					
Rear window washer not working. Handbrake release button missing. Knock in steering, front suspension rattle.					
Road Conditions During Test Drive		Dry			
Engine Timing Mechanism		Timing Chain	1		
Evidence of Can	Evidence of Cam Belt Replacement		No	Kms	
Inspected by:	Troy Smith				
Published by:	Troy Smith		· · ·		
Inspection Date:	16 Nov 2025				

NAME

I have read and understood this condition guide:

SIGNATURE		

1

1

V

2

1

1

Window winder RL Window winder RR

Rear view mirrors

Radio (basic test only)

Sat. nav. (basic test only) Reversing camera

CD (basic test only)

Number of keys

Central locking Remote locking