


Basic Condition Guide

•	Report ID:	27,786,105	Version:	1
	Created:	25 Nov 2025		

Make:	Holden	Model:	Captiva 7		
Body Style:	SUV	Year:	2012		
Rego No.:	GMD149	Rego Expiry:	05 Feb 2026		
WoF Expiry: 22 Aug 2026		Odometer:	225,726 Kms		
Good No.:	27786105	VIN:	KL3CD266JCB058854		
Next Service:	overdue	Service History:	Yes		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					

Key * = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper poor fit. Lichen on roof. Stone chips and scratches

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comments	

Rear brake pads 3mm

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

1 remote nw. Lhs mirror nw. Radio display nw. Felt down on power. Lh main beam nw. Engine is sooty

	Road Conditions During Test Drive		Dry
	Engine Timing Mechanism		Timing Chain
	Evidence of Cam Belt Replacement		Yes No Kms
Inspected by: Gary Adams		Gary Adams	
Published by: Luke Saunders		Luke Saunders	
	Inspection Date:	14 Nov 2025	

I have read and understood
this condition quide:

NAME			

	ОК	Requires Attention	N/A
Engine	OK	Attention	IN/A
Oil level			
Smoke & fumes			
Engine performance		<i>-</i>	
Noise	/		
Coolant condition			
Cooling performance	V V		
Radiator / Hoses (visual)	<u> </u>		
Transmission			
Operation		 	
Noise	<u> </u>		
Clutch			
CV joints	✓		-
	-1		
Wheel bearings			
Brakes		<u> </u>	l e
Performance			
Hand brake	<i>V</i>		
Tyres (lowest observed tread d	epth of		
Left front			4.0 mm
Right front			4.0 mm
Left rear			5.0 mm
Right rear			6.0 mm
Spare	N/A		
Suspension			
Suspension performance	✓		
Steering performance	/		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights		~	
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	✓		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors		~	
Radio (basic test only)		'	
CD (basic test only)	/		
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			1
Reversing camera			1

SIGNATURE		