

# **Basic Condition Guide**

•	Report ID:	27,786,990	Version:	2
	Created:	13 Nov 2025		


	ОК	Requires Attention	N/A
Engine		Accidon	: 1//7
Oil level	1		
Smoke & fumes	/		
Engine performance		~	
Noise	/		
Coolant condition	<b>V</b>		
Cooling performance	✓ ✓		
Radiator / Hoses (visual)	/		
Transmission			
Operation	<b>/</b>		
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes	_		
Performance	1		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			3.5 mm
Right front			4.4 mm
Left rear			5.5 mm
Right rear			5.5 mm
Spare	No		
Suspension			
Suspension performance	/		
Steering performance	<b>/</b>		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	<b>&gt;</b>		
Electrical / Accessories			
Head lights	/		
Tail lights	<b>&gt;</b>		
Indicators	>		
Dashboard warning lights	<b>&gt;</b>		
Wipers (front & rear)	/		
Window winder FL	•		
Window winder FR	<b>/</b>		
Window winder RL	<b>V</b>		
Window winder RR			
Rear view mirrors	/		
Radio (basic test only)	<b>/</b>		
CD (basic test only)	•		
Number of keys	1		
Central locking	<b>✓</b>		
Remote locking	/		
Remote locking  Sat. nav. (basic test only)	•		~

Make:	Mazda	Model:	Atenza
Body Style:	Sedan	Year:	2004
Rego No.:	FKS391	Rego Expiry:	21 Feb 2026
WoF Expiry:	25 Jul 2026	Odometer:	284,759 Kms
Good No.:	27786990	VIN:	7AT0C139X10113238
Next Service:		Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

\* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

#### **Body Inspection Comments**

Right front wing mirror broken Spare wheel missing

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Oil leaks

Interior Comments	
Seats:	Poor
Carpets:	Poor
Panels:	Poor
Dashboard:	Poor

## **General Comments**

Clutch pedal very low Hesitation on acceleration

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Kris Milne	
Published by:	Kris Milne	
Inspection Date:	13 Nov 2025	

I have read and understood	k
this condition quide	

NAME			