

Basic Condition Guide

•	Report ID:	27,787,911	Version:	1	
	Created:	15 Nov 2025			

	Dillei	<u> </u>		Created:	15 Nov 2025				
Make:	Holden	Model:	Cruze				Requires		
Body Style:	Sedan	Year:	2016			OK	Attention	N/A	
Rego No.:	MEQ24	Rego Expiry:	24 Jan 2026	Engine				1	
WoF Expiry:	20 Jul 2026	Odometer:	76,700 Kms	Oil level		/			
Good No.:	27787911	VIN:	6G1PD5EM3GL217185	Smoke & fumes		/			
Next Service:	82,000kms	Service History:	No	Engine performance		/			
Note: This report is not a warranty					Noise				
This report is a guide	only. Consideration is mad	Coolant condition		1					
	ndertaken. The vehicle has b ection prior to purchase an	Cooling performance		1					
Key	,	Radiator / Hoses (visual)							
•	= Rust $C=C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion				
D = Dent P	T = Paint defect P = P	Operation 🗸							
				Noise		1			
		\Box		Clutch				/	
	<u></u>		S	CV joints		•			
				Wheel bea	rings	'			
SD				Brakes					
	IMC II			Performan	ce	/			
				Hand brak	e	1			
	18			Tyres (lowest observed tread depth of tyres)					
				Left front				5 mn	
			(Q)	Right front				5 mn	
				Left rear				4 mn	
)[Right rear				4 mn	
Note: some defects	and blemishes may not be	e displayed in the diagra	am	Spare	Spare Yes				
Body Inspecti	on Comments			Suspensio	n				
				Suspension	n performance	1			
				Steering p	erformance	1			
				Shock abso	orbers	1			
Conditions Du	ring Body Inspection		Wet	Air Condit	ioning / Heater	'			
Under Carriag	ge and Under Bonnet	Inspection Comm	nents	Operation		/			
				Electrical	/ Accessories				
				Head light	S	/			
				Tail lights		1			
Interior Comm	nents			Indicators		1			
Seats:	Average			Dashboard	l warning lights	1			
Carpets:	Average	 			ont & rear)	1			
Panels:	Average				inder FL	1			
Dashboard:	Good		Window w	inder FR	1				
General Com	ments		Window w	inder RL	1				
R rear tyre crac	ked,			Window w	inder RR	1			
				Rear view i		1			
					ic test only)	1			
Road Conditio	ns During Test Drive	Wet	CD (basic t	-	1				
Engine Timing		Number of		1	I				
	m Belt Replacement	Cambelt	No Kms	Central loc	-	1	1	Г	
Inspected by: Marlon Espena						1			
inspected by.				Remote lo	19	ı •	I	1	

I have read and understood this condition guide:

Inspection Date: 15 Nov 2025

Marlon Espena

Published by:

NAME

SIGNATURE

Sat. nav. (basic test only)

Reversing camera