


Basic Condition Guide

Report ID:	27,788,096	Version:	2
Created:	04 Dec 2025		

	OK	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	1		
Engine performance			
Noise	V		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission		1	
Operation	V		
Noise	1		
Clutch	1		
CV joints	V V		
Wheel bearings	1		
Brakes			
Performance	V	I	
Hand brake	1		
Tyres (lowest observed tread of	depth of	tvres)	
Left front			3.9 mm
Right front		-	5.2 mm
Left rear			1.3 mm
Right rear		-	7.7 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater		l .	
Operation	V	I	
Electrical / Accessories		l	
Head lights	V	I	
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			
Number of keys	1	1	
Central locking	1	1	
Remote locking	1	 	
Sat. nav. (basic test only)	<u> </u>		
Reversing camera	1		<u> </u>
neversing Carriera		<u> </u>	

	JIIIEI	<u> </u>			
Make:	LDV	Model:	T60		
Body Style:	Utility	Year:	2017		
Rego No.:	LUL116	Rego Expiry:	08 Dec 2025		
WoF Expiry:	24 Dec 2025	Odometer:	77,900 Kms		
Good No.:	27788096	VIN:	LSFAM11A4HA070346		
Next Service:	18/6/24	Service History:	No		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					
Kev		·			

S = Scratch* = DecalsW = Significant scuffs R = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Stonechips on windscreen Ute tray trim damaged

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Four wheel drive

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Flat tyre warning on but there is no flat tyre Due for service since 18/6/24

Needs the following	ng repaired/replaced	d for wof:	
Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Cameron Senior-A	Arnold	
Published by:	Published by: Devon Brent		
Inspection Date: 1	14 Nov 2025		

۱ŀ	nave	read	and	understo	od
th	is co	nditi	on a	uide.	

NAME			