

-	Report ID:	27,788,915	Version:	1
	Created:	15 Nov 2025		

OK

Requires Attention

•

N/A

				Report ID:	27,788,91	
	ıner	S Basi	c Condition Guide	Created:	15 Nov 20	
Make:	Suzuki	Model:	Carry			
Body Style:	Van	Year:	2007	Facino		
Rego No.:	DWQ698	Rego Expiry:	10 Jul 2026	Oil level		
WoF Expiry:	07 Jul 2026	Odometer:			Smoke & fumes	
Good No.:	27788915	VIN:	7B1VDA63T50300656			
Next Service:	58,000 kms	Service History:	No	Engine performance		
Note: This report is a	not a warranty			Noise	ndition	
This report is a guide of	only. Consideration is made dertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/h	arts have not been dismantled or a from cold. The Vendor recommends a	Coolant condition		
	ction prior to purchase and			Cooling performance		
Key					Hoses (visual	
	= Rust C = C		•	Transmission		
D = Dent PT	= Paint defect $P = Pi$	in dent $SC = Stor$	ne Chips	Operation		
*	S	D *	S D *	Noise		
	CV joints					
s	Wheel bearings					
S A	Brakes					
	$M\Gamma = \Pi^{-1}$		R	Performan	ce	
				Hand brake	е	
D*	Tyres (lowest observed					
				Left front		
			D *	Right front		
SD* SDR* SDR*						
Note: some defects and blemishes may not be displayed in the diagram						
Body Inspection	on Comments			Suspensio	n	
				Suspension	n performan	
				Steering pe	erformance	
				Shock abso	orbers	
Conditions Duri	ng Body Inspection		Dry	Air Condit	ioning / He	
Under Carriage	and Under Ronnet	Inspection Comm	ents	Operation		

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments			
Seats:	Poor		
Carpets:	Poor		
Panels:	Poor		
Dashboard:	Average		

General Comments

Carpet, driver seat torn, driver seat belt frayed, air bent broken, noise driver door strut, rusty body, engine oil leak oil leak, spare tool missing,

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No K	ms
Inspected by:	Marlon Espena		
Published by:	Marlon Espena		
Inspection Date:	15 Nov 2025		

I have read and understood
this condition guide:

NAME			

Hadiator / Froses (Visual)			
Transmission			
Operation	/		
Noise	/		
Clutch	/		
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	1		
Hand brake	~		
Tyres (lowest observed tread d	lepth of	tyres)	
Left front			3 mm
Right front			3 mm
Left rear			7 mm
Right rear			7 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	1		
Shock absorbers	1	ĺ	
Air Conditioning / Heater	,	•	•
Operation			V
Electrical / Accessories			
Head lights	1		
Tail lights	1		
Indicators	~		
Dashboard warning lights	/		
Wipers (front & rear)	\(\tau \)		
Window winder FL	1		
Window winder FR	1		
Window winder RL			1
Window winder RR			1
Rear view mirrors	1	ĺ	
Radio (basic test only)		~	
CD (basic test only)			1
Number of keys	1		
Central locking			'
Remote locking			1
Sat. nav. (basic test only)			1
Reversing camera			1
-			

SIGNATURE			