


Basic Condition Guide

Report ID: 27,789,		27,789,806	Version:	1
	Created:	19 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	V V		
Noise	/		
Coolant condition			
Cooling performance	1		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			
CV joints	✓		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		6	6.5 mm
Right front		2	2.5 mm
Left rear			1.0 mm
Right rear			1.0 mm
Spare	N/A		
Suspension			
Suspension performance			
Steering performance			
Shock absorbers			
Air Conditioning / Heater		ı	
Operation	✓		
Electrical / Accessories		ı	
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	<u>/</u>		
Wipers (front & rear)	/		
Window winder FL	<u> </u>		
Window winder FR	✓		
Window winder RL			
Window winder RR			<u> </u>
Rear view mirrors			
Radio (basic test only)			
CD (basic test only)	1		<u> </u>
Number of keys	1	Γ	
Central locking	<u> </u>		
Remote locking	•		
Sat. nav. (basic test only)			
Reversing camera			

Make:	Volvo	Model:	C30
Body Style:	Hatchback	Year:	2010
Rego No.:	LHN849	Rego Expiry:	15 Nov 2026
WoF Expiry:	12 Jun 2026	Odometer:	95,394 Kms
Good No.: 27789806		VIN:	YV1MK434BA2211301
Next Service: 101,563		Service History:	No
diagnostic testing un	only. Consideration is ma Idertaken. The vehicle has		arts have not been dismantled or h from cold. The Vendor recommends a

itey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Headlights yellow. Left washer cover missing from front bumper Left corner popped out front bumper

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Oil leak

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Road Condition	s During Test Drive	Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by: Samuel Weir			
Published by:	Brandon Willmore)	
Inspection Date:	18 Nov 2025		

have read and understood
this condition quide

NAME		

3	IG	N	Δ٦	ГU	R	F	