

Basic Condition Guide

Report ID:	27,791,083	Version:	2
Created:	19 Nov 2025		

Basic Condition Guide						
Make:	Holden	Model:	Colorado			
Body Style:	Utility	Year:	2018			
Rego No.:	LET299	Rego Expiry:	27 Feb 2026			
WoF Expiry:	25 Feb 2026	Odometer:	94,053 Kms			
Good No.:	27791083	VIN:	MMU148EK0JH633723			
Next Service:	98000	Service History:	Yes			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						
Key- $S = Scratch$ $R = Rust$ $C = Crack$ $* = Decals$ $W = Significant scuffs$ $D = Dent$ $PT = Paint defect$ $P = Pin dent$ $PT = Paint defect$						
S SC P SC W D W D SC W						

SSC	P SC W D W	D SC W
SC W		SR
S D SC	S SC S D	S

Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Driver door check strap clicking

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Com	nents

Interior Comments		
Seats: Average		
Carpets: Average		
Panels: Average		
Dashboard:	holes on centre console	
General Comments		

Partial service history

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Sione Mae	
Published by:	Bruce Screaton	
Inspection Date:	15 Nov 2025	

I have read and understood
this condition quide.

NAME			

	ОК	Requires Attention	N/A
Engine	OK	Attention	IN/A
Oil level	V		
Smoke & fumes			
Engine performance	<u> </u>		
Noise	<u> </u>		
Coolant condition			
Cooling performance	V V V		
Radiator / Hoses (visual)			
Transmission	•	l	<u> </u>
Operation		l	<u> </u>
Noise	~		
Clutch			
CV joints	✓		
Wheel bearings	~		
Brakes			
Performance			Π
Hand brake			
Tyres (lowest observed tread d	enth of	l tvres)	
Left front	Сригог	· ·	6.0 mm
Right front			5.0 mm
Left rear			6.0 mm
Right rear			5.0 mm
	Yes		
Spare Suspension	163		
Suspension performance	1	Ι	
Steering performance	<u> </u>		
Shock absorbers	<u> </u>		
Air Conditioning / Heater			
Operation	<i></i>		
Electrical / Accessories			
Head lights	<u> </u>	l .	1
Tail lights	~		
Indicators	~		
Dashboard warning lights			
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	·		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			
Number of keys	2	I	Ь
Central locking		I	<u> </u>
	<u>,</u>		
Remote locking			
Sat. nav. (basic test only)			_
Reversing camera		l	

IGNATURE		