

Basic Condition Guide

•	Report ID:	27,791,446	Version:	3
	Created:	10 Dec 2025		

	Dillei	<u> </u>		Created: 10 Dec 2025		,		
Make:	Mitsubishi	Model:	Pajero Sport			Requires		
Body Style:	SUV	Year:	2021		OK	Attention	N/A	
Rego No.:	NSD19	Rego Expiry:	19 Aug 2026	Engine				
	24 Oct 2026	Odometer:	133,979 Kms	Oil level	/			
WoF Expiry: Good No.:	27791446	VIN:	MMAGUKS10MH007200	Smoke & fumes	/			
Next Service:	142000 kms		Yes	Engine performance	/			
		Service History:	Noise	/				
Note: This report is This report is a guide	only. Consideration is mad	le for age and mileage. Pa	Coolant condition		/			
diagnostic testing un full mechanical inspe	dertaken. The vehicle has bection prior to purchase ar	peen driven up to 50km/l nd this can be arranged f	Cooling performance	/				
Key		1	Radiator / Hoses (visual)	/				
•	= Rust C = C	Crack *= Deca	Transmission					
D = Dent P1	$\Gamma = Paint defect P = Paint defect$	Pin dent SC = Sto	ne Chips	Operation	/			
S		SP SP	SD	Noise	/			
		31	Clutch			V		
			S SC W	CV joints	V			
	MA UN			Wheel bearings	V			
S SC W				Brakes				
	M 11.			Performance	V			
			D	Hand brake	1			
SPSC	R			Tyres (lowest observed tread depth of tyres)				
			Left front	5.0 mm				
			SP	Right front		6	3.0 mn	
		Left rear	6.0 mm					
SSC		Right rear	5.0 mm					
Note: some defects	and blemishes may not be	e displaved in the diagra	nm	Spare	Yes			
Body Inspection				Suspension				
Centre console	lid torn, RF seat torn	, cargo blind missin	g, roof rack key missing,	Suspension performance	V			
windscreen crae	ck, coolant low,			Steering performance	1			
				Shock absorbers	1			
Conditions Dur	ring Body Inspection		Air Conditioning / Heater					
	e and Under Bonne	t Inspection Comm	Operation	V				
		•		Electrical / Accessories				
				Head lights	V			
				Tail lights	1			
Interior Comm	nents			Indicators	1			
Seats:	Average			Dashboard warning lights	1			
Carpets:	Average		·	Wipers (front & rear)	1			
Panels:	Average	Window winder FL	1					
Dashboard:	Average	Window winder FR	1					
General Comm	_		Window winder RL	1				
20110101				Window winder RR	1			
				Rear view mirrors	1			
				Radio (basic test only)	1			
Road Condition	ns During Test Drive	Dry	CD (basic test only)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
Engine Timing		Number of keys	2					

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 20 Nov 2025

Will Dewey

Henry Manders

NAME

Yes

No

SIGNATURE

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1

Kms