

## **Basic Condition Guide**

Report ID:	27,791,678	Version:	1
Created:	20 Nov 2025		

1

1

1

1 1

3

1

Tail lights

Indicators

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Requires Attention

N/A

5.5 mm 6 mm 7 mm 7 mm

			a Canaditian Cuida				
	ntuer	S Basi	c Condition Guide	Created:	20 Nov 2025		
Make:	Volkswagen	Model:	T5	-		OK	Requ Atter
Body Style:	Van	Year:	2011	Engine		UK	Atter
Rego No.:	GAM998	Rego Expiry:	30 Aug 2026	Oil level		1	
WoF Expiry:	25 Jan 2026	Odometer:	263,819 Kms	Smoke & f	umes	1	
Good No.:	27791678	VIN:	WV1ZZZ7HZBH131392			1	
Next Service:	283000	Service History:	No	Engine performance Noise		1	
lote: This report is not a warranty				Coolant condition		1	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling performance		1	
				31		1	
(ey				Radiator / Hoses (visual)			
	R = Rust C = C			Transmission Operation		Т	
= Dent	PT = Paint defect P = Paint defect	in dent SC = Stor	ne Cnips	Operation		1	
P SC		SD SD	SDR	Noise		<b>V</b>	
				Clutch CV joints			
S						1	
S D /		<u> </u>		Wheel bearings		/	<u> </u>
Albania de la constanta de la				Performar		1	T
							-
	Hot II			Hand brake			
DR				Tyres (lowest observed tread depth of tyr			tyres)
			SD	Left front			
				Right from	t		
SP	S	DR SDW	SDR	Left rear			
		DK JCDW		Right rear			
Note: some defects and blemishes may not be displayed in the diagram			Spare		Yes		
, ,	tion Comments			Suspension	on		
Right mirror cover refit, RF door seal torn, passenger seat belt fraying & twisted, LF seat stalk damaged, LR tyre sidewall damage, rear wheel steel rim damage			Suspensio	n performance	/		
			Steering p	erformance	/		
				Shock abs	orbers	/	
Conditions D	uring Body Inspection		Dry	Air Condi	tioning / Heater		
FWD Engine oil leak, surface rust underside			Operation		/	L	
			Electrical	/ Accessories			
			Head light	:S	/		

Interior Comments		
Seats:	torn & stains	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Master window switch acting up, beeping noise when vehicle is running

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Unknown		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Arunachalam Subramanian			
Published by:	Arunachalam Subramanian			
Inspection Date:	20 Nov 2025			

I have read and understood		
this condition guide:	NAME	

SIGNATURE			

	Sat. nav. (basic test only)		, v
	Reversing camera		/
:	SIGNATURE		