

•	Report ID:	27,791,970	Version:	2
	Created:	23 Dec 2025		

	ntuet	S Basi	c Condition Guide	Created:	23 Dec 2025		
Make:	Mercedes-Benz	Model:	Sprinter				
Body Style:	Van	Year:	2021	Engino			
Rego No.:	RJS148	Rego Expiry:	28 Dec 2025	Engine Oil level			
WoF Expiry:	10 Jan 2026	Odometer:	64,415 Kms	Smoke & fu	umos		
Good No.:	27791970	VIN:	W1V9076332P332428				
Next Service:	79000km	Service History:	No		Engine performance		
Note: This report is	not a warranty			Noise Coolant condition			
This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling performance			
full mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.				
Кеу					Radiator / Hoses (visual)		
	$= Rust \qquad C = C$			Transmission			
D = Dent P	Γ = Paint defect $P = P$	in dent SC = Sto	ne Chips	Operation			
SC		D D	SC	Noise			
				Clutch			
	\sim			-	CV joints		
		<u> </u>		Wheel bearings			
$ \beta$				Brakes			
1		11	D P SC W	Performan			
				Hand brake			
P SC				Tyres (lowest observed tread			
			SD	Left front			
D D SC					Right front Left rear		
			Right rear				
Note: some defects and blemishes may not be displayed in the diagram					Spare		
Body Inspection Comments					Suspension		
2nd row centre and 3rd row right seat belts fraying on face. Service and handbooks missing.				Suspension performance			
moonig.				Steering p	erformance		
				Shock abso			
	ring Body Inspection		Dry	Air Condit	tioning / Heater		
	e and Under Bonnet	Inspection Comm	nents	Operation			
RWD.				Electrical	/ Accessories		
				Head light	S		
				Tail lights			
Interior Comn	nents			Indicators			

		Requires	
	ОК	Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Engine performance	~		
Noise	~		
Coolant condition	~		
Cooling performance	~		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			/
CV joints	/		
Wheel bearings	~		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		4	1.0 mm
Right front		6	3.0 mm
Left rear		6	3.0 mm
Right rear		6	3.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	1		
Tail lights	1		
Indicators	~		
Dashboard warning lights	1		
Wipers (front & rear)	~		
Window winder FL	1		
Window winder FR	V		
Window winder RL	•		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	3		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			-
Reversing camera	1		
-			

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by: Sharnae Smith				
Published by:	Henry Manders			

I have read and understood
this condition guide:

Inspection Date: 24 Nov 2025

Good

Good

Good

Good

Seats:

Carpets:

Panels: Dashboard:

General Comments

NAME			

NATURE		