

Basic Condition Guide

Report ID:	27,791,991	Version:	2
Created:	26 Nov 2025		


	OK	Requires Attention	N/A
Engine	OIL	Accention	14//1
Oil level	V		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			<u> </u>
Operation	·	1	
Noise	1		
Clutch	<u> </u>		1
CV joints	1		
Wheel bearings	· /		
Brakes			<u> </u>
Performance	<i>J</i>		
Hand brake	1		
Tyres (lowest observed tread of	denth of	turas)	
Left front	Геритог		5.0 mm
Right front			6.0 mm
Left rear			0.0 mm
			9.0 mm
Right rear	Yes	-	9.0 111111
Spare Suspension	165		
Suspension performance	<i>J</i>		1
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V	l	1
Electrical / Accessories			<u> </u>
Head lights	· ·	l	1
Tail lights	1		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear)	V		
Window winder FL	V		
Window winder FR	V		
Window winder RL			J
Window winder RR			<i>\'\'</i>
Rear view mirrors	1		
Radio (basic test only)	V		
	1		
CD (basic test only)	3	l	<u> </u>
Number of keys Control locking	<i>y</i>	1	1
Central locking	V		
Remote locking			<u></u>
Sat. nav. (basic test only)	·		
Reversing camera		I	I

Make:	Toyota	Model:	Hiace		
Body Style:	Van	Year:	2016		
Rego No.:	JQA844	Rego Expiry:	28 Feb 2026		
WoF Expiry:	16 Feb 2026	Odometer:	186,826 Kms		
Good No.:	27791991	VIN:	JTFPT22P200016848		
Next Service:	190,000km	Service History:	No		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or					

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

\mathbf{v}	~~.
n	eν

rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

High stop light cracked. R bumper cracked. Tools missing. Mobility ramp installed. RF Seat base pad torn. F bumper left trim missing. RF&LF door mirrors gouged. LR wheel centre cap and trim missing. LF tyre sidewall cracking. L sill dented. Bootlid large dents. Rusty roof.

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Surface rust beginning to form under radiator.

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

RWD.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Sharnae Smith			
Published by:	Sharnae Smith			
Inspection Date:	24 Nov 2025			

I have read and understood
this condition guide:

NAME			