

Basic Condition Guide

Report ID:	27,792,157	Version:	1
Created:	10 Dec 2025		

lake:	Honda	Model:	CRV
ody Style:	Wagon	Year:	2006
lego No.:	HMM536	Rego Expiry:	15 Mar 2026
VoF Expiry:	08 Nov 2026	Odometer:	156,173 Kms
Good No.:	27792157	VIN:	7AT08G7HX14001795
lext Service:	166,000 km	Service History:	No
gnostic testing un mechanical inspo y	only. Consideration is mad dertaken. The vehicle has b ection prior to purchase an	een driven up to 50km/ d this can be arranged f 	
	= Rust $C = C$ $\Gamma = Paint defect P = P$	in dent SC = Sto	ne Chips
SPT	W	PT C S PT SC	SC
			S SC
sc /			
J	18		
1	M = 1		
sc			
sc	W	SC P SC	
		disclosed in the discou	
	and blemishes may not be on Comments	displayed in the diagra	am
	p outside of critical vis	sion area.	
			Ì
onditions Dur	ring Body Inspection		Dry
	ring Body Inspection e and Under Bonnet	Inspection Comm	
nder Carriag	e and Under Bonnet	Inspection Comm	
	e and Under Bonnet	Inspection Comm	
Inder Carriag eshly serviced ont wheel driv	d. ve.	Inspection Comm	
nder Carriag eshly serviced ont wheel driv nterior Comm	e and Under Bonnet d. ve.	Inspection Comm	
eshly serviced ont wheel driv oterior Comments:	d. ve. Average	Inspection Comm	
eshly serviced ont wheel driv oterior Comme eats:	ne and Under Bonnet d. ve. nents Average Good	Inspection Comm	
eshly serviced ent wheel driving terior Comme eats: arpets: unels:	ne and Under Bonnet d. ve. Average Good Good	Inspection Comm	
eshly serviced ont wheel driventerior Commeterior Comm	ne and Under Bonnet d. ve. nents Average Good Good Good	Inspection Comm	
eshly serviced ont wheel driventerior Commeterior Comm	ne and Under Bonnet d. ve. hents Average Good Good Good Good ments	Inspection Comm	
eshly serviced ont wheel driventerior Commeterior Comm	ne and Under Bonnet d. ve. hents Average Good Good Good Good ments	Inspection Comm	
Inder Carriag	ne and Under Bonnet d. ve. hents Average Good Good Good Good ments	Inspection Comm	
eshly serviced ont wheel drivent wheel drivent wheel drivent wheel drivent wheel drivent wheels: arpets: arpets: ashboard: eneral Communication of the c	ne and Under Bonnet d. ve. hents Average Good Good Good Good ments	Inspection Comm	

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	\(\frac{1}{V} \)		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	~		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread de	epth of	tyres)	
Left front			1.0 mm
Right front		6	6.0 mm
Left rear		6	6.0 mm
Right rear		(6.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)		'	
CD (basic test only)	/		
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			1
Reversing camera			V

have read and understood
this condition quide

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 17 Nov 2025

Imraan Bryant

Erin White

N	Δ	M	F	

Yes

No

SIGNATURE

Kms