

Report ID:	27,792,709	Version:	1
Created:	06 Dec 2025		

Basic Condition Guide								
	ome	<u> </u>	——————————————————————————————————————	Created:	06 Dec 2025			
Make:	Honda	Model:	FIT				Requires	
Body Style:	Hatchback	Year:	2014			OK	Attention	N/A
Rego No.:	RMH42	Rego Expiry:	30 Apr 2026	Engine				
WoF Expiry:	14 Nov 2026	Odometer:	92,455 Kms	Oil level 🗸				
Good No.:	27792709	VIN:	7AT08G2YX25043409	Smoke & fumes				
Next Service:	102,000 km	Service History:	No	Engine pe	rformance	<b>/</b>		
lote: This report is				Noise		/		
his report is a quide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant co		/		
ilagnostic testing un ull mechanical inspe	ection prior to purchase an	d this can be arranged f	h from cold. The Vendor recommends a or an additional charge.		erformance	/		
Кеу					Hoses (visual)	<b>/</b>		
S = Scratch R	= Rust $C=C$	irack *= Deca	ls W = Significant scuffs	Transmiss	sion		1	
D = Dent P1	$\Gamma = Paint defect  P = P$	in dent SC = Sto	ne Chips	Operation		/		
PT	C	sc sc		Noise		/		
$\overline{}$	$\overline{}$	$\top$		Clutch				/
	(M)-		SC	CV joints		/		
SC (				Wheel bea	arings	/		
				Brakes				
			PT	Performar	ice	<b>'</b>		
				Hand brak	e	/		
sc	M - I			Tyres (lowest observed tread depth of tyres)				
				Left front		7.0 mm		7.0 mm
				Right fron	t		7	7.0 mm
				Left rear			7	7.0 mm
		P D	S	Right rear			7	7.0 mm
lote: some defects	and blemishes may not be	displayed in the diagra	am	Spare		N/A		
Body Inspection	on Comments			Suspension	on			
				Suspensio	n performance	/		
				Steering p	erformance	/		
				Shock abs	orbers	1		
Conditions Dur	ring Body Inspection		Dry	Air Condi	tioning / Heater			
Under Carriage and Under Bonnet Inspection Comments						/		
FWD,				Electrical	/ Accessories			
				Head light	S		V	
				Tail lights		V		
Interior Comments				Indicators		1		
Seats: Good		Dashboard	d warning lights	1				
Carpets:	: Good		Wipers (fro	ont & rear)	1			
Panels:			Window w	vinder FL	1			
Dashboard: Good		Window w	vinder FR	1				
General Comments				Window w	vinder RI	1		

Interior Comments				
Seats:	Good			
Carpets:	Good			
Panels:	Good			
Dashboard:	Good			
General Comments				

R/F park light not working, Radio has no signal,

Road Condition	s During Test Drive	Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Imraan Bryant	
Published by:	Erin White	
Inspection Date:	18 Nov 2025	

have read and understood
this condition quide

NAME			

SIGNATURE			

•

V

1

1

1

Window winder RR Rear view mirrors

Radio (basic test only)

Sat. nav. (basic test only) Reversing camera

CD (basic test only)

Number of keys

Central locking Remote locking