

•	Report ID:	27,792,745	Version:	3
	Created:	11 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	V		
Engine performance	\( \times \)		
Noise	V		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	V		
Noise	1		
Clutch			~
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	
Left front			5.0 mm
Right front			5.0 mm
Left rear			5.0 mm
Right rear		(	6.0 mm
Spare	N/A		
Suspension			
Suspension performance	V		
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	\( \times \)		
Window winder FL	~		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	2		
· · · · · · · · · · · · · · · · · · ·	<b>/</b>		1
Central locking	V		
· · · · · · · · · · · · · · · · · · ·	V		V

Make:	Mitsubishi	Model:	Galant
Body Style:	Sedan	Year:	2008
Rego No.:	NJU724	Rego Expiry:	19 Sep 2026
WoF Expiry:	25 Dec 2026	Odometer:	128,106 Kms
Good No.:	27792745	VIN:	7AT0CJ0JX21200670
Next Service:	135,000	Service History:	Yes

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

# **Body Inspection Comments**

Headlights faded. Factory tyre inflation kit provided (no spare). Paint cracked/flaking in places.

Conditions During Body Inspection	Wet		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
Committee		

## **General Comments**

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Finlay Lemmens	
Published by:	Laura lovine	
Inspection Date:	18 Nov 2025	

I hav	ve read	and	understood
thic	conditi	on a	uide.

NAME			

SI	GN	AT	URF	