

## **Basic Condition Guide**

•	Report ID:	27,792,922	Version:	1
	Created:	27 Nov 2025		


	ОК	Requires Attention	N/A
Engine	OK	Accention	14//1
Oil level	/		
Smoke & fumes	1		
Engine performance	/		
Noise	-	·	
Coolant condition		-	
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation			
Noise	1		
Clutch			
CV joints	1		<u> </u>
Wheel bearings	1		
Brakes			
Performance	./		
	•		
Hand brake			
Tyres (lowest observed tread d	epth of		
Left front			5.5 mm
Right front			5.5 mm
Left rear			3.0 mm
Right rear			3.5 mm
Spare	Yes		
Suspension	_		
Suspension performance	/		
Steering performance	1		
Shock absorbers	/		
Air Conditioning / Heater		1	
Operation		<b>/</b>	
Electrical / Accessories			
Head lights	~		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	/		
Window winder RL	/		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	1		
Central locking	1		
Remote locking		~	
Sat. nav. (basic test only)			<b>'</b>
Reversing camera			1
<u> </u>			

Make:	Nissan	Model:	Bluebird	
Body Style:	Sedan	Year:	2005	
Rego No.:	HMQ923	Rego Expiry:	01 Jul 2026	
WoF Expiry:	02 Jun 2026	Odometer:	152,193 Kms	
Good No.:	27792922	VIN:	7AT0DH1EX14185482	
Next Service: 162194 Service History: No				
Note: This report is r	not a warranty			
his report is a quide only. Consideration is made for age and mileage. Parts have not been dismantled or				

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

$\mathbf{v}$	~~.
n	eν

ney				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Minor stone chips on windscreen

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Front wheel drive

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

## **General Comments**

A/C does not go cold Slight ticking noise Key remote not operating

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jaykib Collins	
Published by:	Janine Bell	
Inspection Date:	16 Nov 2025	

I have read and understood
this condition auide:

NAME			