

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,793,010 | Version: | 2 |
| Created: | 24 Nov 2025 | | |


| | | | |
|---------------|-------------|------------------|------------------|
| Make: | Ford | Model: | Ecosport |
| Body Style: | SUV | Year: | 2015 |
| Rego No.: | JNF404 | Rego Expiry: | 21 Dec 2025 |
| WoF Expiry: | 13 Nov 2026 | Odometer: | 61,637 Kms |
| Good No.: | 27793010 | VIN: | MAJBXXMRKBF26179 |
| Next Service: | 68,459 | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Wet

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

| | |
|------------|---------|
| Seats: | Average |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Average |

General Comments

1 out of 2 keys doesn't have a remote.

| | |
|-----------------------------------|---|
| Road Conditions During Test Drive | Wet |
| Engine Timing Mechanism | Cambelt |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Kms |
| Inspected by: | Finlay Lemmens |
| Published by: | Anna Zandstra |
| Inspection Date: | 18 Nov 2025 |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____

| | OK | Requires Attention | N/A |
|---|----|--------------------|--------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | | 4.0 mm |
| Right front | | | 5.0 mm |
| Left rear | | | 7.0 mm |
| Right rear | | | 7.0 mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | ✓ | | |