

•	Report ID:	27,793,023	Version:	1	
	Created:	28 Nov 2025			

UT	urner	S Basi	c Condition Guide	Created:	27,793,023 28 Nov 2025	ve	rsion: 1	
Make:	Ford	Model:	Ranger				Requires	
Body Style:	Utility	Year:	2013			OK	Attention	N/A
Rego No.:	GUG758	Rego Expiry:	25 Oct 2026	Engine			i	1
WoF Expiry:	10 May 2026	Odometer:	171,274 Kms	Oil level		/		
Good No.:	27793023	VIN:	MNAUMFF50DW173206	Smoke & fumes		-		
Next Service:	174,240	Service History:	Yes	Engine per	formance	/		
				Noise /				
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					ndition	/		
					rformance	/		<u> </u>
Key				Radiator / F	Hoses (visual)	/	L	
= Scratch F	R = Rust $C = C$	Crack *= Deca	ls W = Significant scuffs	Transmissi	ion			
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips				Operation		/		<u> </u>
sc		sc sc	SC	Noise		/		
	$\overline{}$	T		Clutch				~
	() () () () () () () () () ()			CV joints				1
SC W	THE W	+		Wheel bear	rings	/		
SC W				Brakes				
					ce	/		
					9	/		
SC				Tyres (lowest observed tread depth of tyres)				
						7.0 m		
				Right front		7.0 m		7.0 m
				Left rear		7.0		7.0 m
		R SC SC		Right rear		7.0 m		
ote: some defect	s and blemishes may not be	e displayed in the diagra	am	Spare		Yes		
Body Inspect	tion Comments			Suspension				
Headlights fad	ed.			Suspension	performance	/		
				Steering pe	erformance	1		
				Shock abso	orbers	1		
Conditions Du	uring Body Inspection		Wet	Air Conditioning / Heater				
Under Carria	ge and Under Bonnet	Inspection Comm	nents	Operation		V		
	-		<u>, </u>	Electrical / Accessories				
				Head lights		V		
				Tail lights		1		
Interior Comments				Indicators		/		
Seats:					warning lights	1		
Carpets:	Average			Wipers (fro		1		
Panels:	Average			Window wi		1		
Dashboard:	glovebox handle	worn.		Window wi		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
General Com				Window wi		1	-	
Certeral Coll	inches			Window wi		1		
				WITHOW WI	inder nn		<u> </u>	

Road Conditions During Test Drive		Wet		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Finlay Lemmens			
Published by:	Anna Zandstra			
Inspection Date:	18 Nov 2025			

SIGNATURE			

1

1 2

1

1

Rear view mirrors Radio (basic test only)

CD (basic test only)

Sat. nav. (basic test only)

Reversing camera

Number of keys

Central locking Remote locking