

## **Basic Condition Guide**


•	Report ID:	27,793,262	Version:	1
	Created:	20 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	<b>V</b>		
Noise	1		
Coolant condition	<b>V</b>		
Cooling performance	1		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	1		
Clutch			~
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	/		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tvres)	
Left front		,,	6 mm
Right front			6 mm
Left rear			2 mm
Right rear			3 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater	-		
Operation	1		
Electrical / Accessories	_		
Head lights	1		
Tail lights	1		
Indicators	1		
Dashboard warning lights	~		
Wipers (front & rear)	1		
Window winder FL	<b>V</b>	<del>                                     </del>	
Window winder FR	<b>V</b>	-	
Window winder FK Window winder RL	~		
Window winder RR	1		
Rear view mirrors	~		
	1		
Radio (basic test only)	1	<del> </del>	
CD (basic test only)	2		<u> </u>
Number of keys	- Z	Ī	
Central locking	1	-	
Remote locking		-	
Sat. nav. (basic test only)		-	
Reversing camera		<u> </u>	

Make:	Toyota	Model:	Camry
Body Style:	Sedan	Year:	2004
Rego No.:	RLK534	Rego Expiry:	28 Dec 2025
WoF Expiry:	15 Sep 2026	Odometer:	154,876 Kms
Good No.:	27793262	VIN:	6T153XK360X294431
Next Service:	163,000km	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key \* = DecalsR = RustC = CrackW = Significant scuffs S = ScratchD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Windscreen stone chips

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Underbody surface rust Engine oil leak Front wheel drive

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive Dry Cambelt **Engine Timing Mechanism ✓** No Evidence of Cam Belt Replacement Yes Kms Rowan Fey Inspected by: Published by: Rowan Fey Inspection Date: 20 Nov 2025

I	have read	and	understo	od
t	his conditi	on o	uide.	

NAME			