

Basic Condition Guide

•	Report ID:	27,794,426	Version:	2
	Created:	25 Nov 2025		

	Diffe	<u> </u>		Created:	25 Nov 2025					
Make:	Mazda	Model:	Mazda3				Requires			
Body Style:	Hatchback	Year:				OK	Attention	N/A		
	lego No.: HLG396 Rego Expiry:		27 Oct 2025	Engine			<u> </u>			
WoF Expiry:	06 Dec 2026	Odometer:	107,679 Kms	Oil level						
Good No.:	27794426	VIN:			umes	✓				
Next Service:	116000kms	Service History:		Engine pe	rformance	<i>\</i>				
Note: This report is		Noise		<u> </u>						
This report is a guide	only. Consideration is mad	Coolant co	ondition	✓						
diagnostic testing ur full mechanical insp	ndertaken. The vehicle has be ection prior to purchase an	peen driven up to 50kn nd this can be arranged	Cooling pe	erformance	/					
Key		Radiator /	Hoses (visual)	/						
•	= Rust $C=C$	Crack *= Dec	als W = Significant scuffs	Transmiss	Transmission					
D = Dent P	Γ = Paint defect $P = P$	Pin dent $SC = St$	one Chips	Operation		•				
Р			P	Noise		•				
	$\overline{}$	\top		Clutch				~		
	<u></u>			CV joints		•				
		+		Wheel bea	arings	•				
S				Brakes	Brakes					
			R SC	Performar	ice	/				
			K SC	Hand brak	ie	/				
SC	18	<u></u>		Tyres (low	Tyres (lowest observed tread depth of tyres)					
				Left front		7 mm				
			(Q)	Right from	t	7 mm				
				Left rear		3.5 mm				
		P		Right rear		4.0 mm				
Note: some defects	and blemishes may not be	e displayed in the diac	ram	Spare		Yes				
	on Comments			Suspension	on					
				Suspensio	n performance	/				
				Steering p	erformance	/				
				Shock abs	orbers	/				
Conditions Du	ring Body Inspection			Air Condi	Air Conditioning / Heater					
	e and Under Bonnet	t Inspection Com	ments	Operation		/				
		. · ·		Electrical	Electrical / Accessories					
				Head light	is .	/				
				Tail lights		/				
Interior Comn	nents			Indicators		·				
Seats:	Good			Dashboard	d warning lights					
Carpets:	Good			Wipers (fro		V				
Panels: Good				Window w		V				
Dashboard: Good				Window w		·				
General Comr		Window w		·						
	ebox for service work		Window w		·					
5.500 iii giov				Rear view		·				
						· ·				
Poad Com dist	os Durina Tost Dai	Dry			sic test only)	•	-	_		
	ns During Test Drive		CD (basic to Number o		1	<u> </u>				
Engine Timing Mechanism Timing Chain Evidence of Cam Belt Replacement Yes No Kms							1	ĺ		
		Yes	No Kms	Central loc		<u>/</u>				
Inspected by:	Kilipati Mae			Remote lo	cking	/	1	1		

I have read and understood this condition guide:

Inspection Date: 19 Nov 2025

Published by:

NAME _

Neil Honeyman

SIGNATURE

Sat. nav. (basic test only)

Reversing camera