

•	Report ID:	27,795,186	Version:	2
	Created:	27 Nov 2025		

		C Basi	c Condition Guide		2.,.00,.00		_	
	nuel			Created:	27 Nov 2025			
Make:	Ford	Model:	Transit	Requires				
Body Style:	Minibus	Year:	2018	OK Attention		Attention	N/A	
Rego No.:	LFW397	Rego Expiry:	06 Mar 2026	Engine Oil level		/		
WoF Expiry:	14 May 2026	Odometer:	184,721 Kms	Smoke & fu	ımas	'		
Good No.:	27795186	VIN:	WF0HXXTTGHHE61174	Engine per				
Next Service:	147,000kms	Service History:	No	Noise	Torritatice			
Note: This report is a	not a warranty	•	·	Coolant co	ndition	· ·		
liagnostic testing un	dertaken. The vehicle has b	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling pe		· ·		
ull mechanical inspe	ection prior to purchase and	d this can be arranged for	or an additional charge.		Hoses (visual)	<i>'</i>		
Key	D			Transmiss				
	= Rust $C = C$ = Paint defect $P = Pi$			Operation		/		
	- rume defect 1 - 11	mucht 5e-5tol	nic Criips	Noise		1		
SD			SD	Clutch		/		
				CV joints		/		
			SD	Wheel bea	rinas	~		
Я				Brakes				
	Pr \			Performan	ce	1		
				Hand brak	2	1		
	R			Tyres (lowest observed tread depth of tyres)				
				Left front 8.0 mm				
			(Q)	Right front		8.0 mm		
	\angle			Left rear		7.0 mm		
)[S D		Right rear			7	7.0 mm
Note: some defects a	and blemishes may not be	displayed in the diagra	nm	Spare		Yes		
Body Inspection	on Comments			Suspensio	n			
Rear wiper blad	e worn, r rear side pa	nel big dent.steerir	ng wheel worn.service overdue	Suspension	n performance	~		
				Steering p	erformance	1		
				Shock abso	orbers	1		
Conditions During Body Inspection Dry			Air Conditioning / Heater					
Under Carriage	Under Carriage and Under Bonnet Inspection Comments			Operation		•		
				Electrical / Accessories				
				Head light	5	/		
				Tail lights		1		

Dry
ents

Interior Comments				
Seats:	Average			
Carpets:	Average			
Panels:	Average			
Dashboard:	Average			
- I				

General Comments

Missing spare tools, second row seat torn and second row R end seat belt not retractable, left front seat belt torn, sliding body seal torn and not secured, tail gate can't open, engine oil leak, drive shaft rust,

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chai	n	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Marlon Espena			
Published by:	Henry Manders			
Inspection Date:	18 Nov 2025			

I have read	and	lunc	lerstoo	d
this condit	ion g	guide	2:	

NAME			

SIGNATURE		

Reversing camera

Tail lights	 		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear)		/	
Window winder FL			~
Window winder FR			~
Window winder RL			~
Window winder RR			1
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		•
Central locking	~		
Remote locking	~		
Sat. nav. (basic test only)			~