

Report ID:	Report ID: 27,795,642		1
Created:	19 Nov 2025		

		Dooi	a Canditian Cuida	Report ID:	27,79
	ntuet	S Basi	c Condition Guide	Created:	19 No
Make:	Hyundai	Model:	130		
Body Style:	Wagon	Year:	2019	Engine	
Rego No.:	MPD634	Rego Expiry:	21 Jul 2026	Engine	
WoF Expiry:	03 Dec 2026	Odometer:	149,535 Kms	Oil level	
Good No.:	27795642	VIN:	TMAH3815MLJ061381	Smoke & fu	
Next Service:	157,206 Kms	Service History:	Yes	Engine per	forman
Note: This report is	not a warranty			Noise	
			arts have not been dismantled or h from cold. The Vendor recommends a	Coolant condition	
full mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.	Cooling performa	
Key				Radiator / Hoses (\	
	= Rust $C = C$		ls W = Significant scuffs	Transmission	
D = Dent P	T = Paint defect P = Paint defect	in dent SC = Sto	ne Chips	Operation	
SC		D		Noise	
	$\overline{}$	$\top$		Clutch	
	(A)-			CV joints	
W				Wheel bearings	
W A				Brakes	
	Performance				
				Hand brake	
SC				Tyres (lowest obse	
				Left front	
				Right front	
				Left rear	
PT D D PT P					
Note: some defects	and blemishes may not be	displayed in the diagra	am	Spare	
Body Inspecti	on Comments			Suspensio	n
Rear taillights of	chipped			Suspension	n perfor
				Steering pe	erforma
				Shock abso	rbers
Conditions Du	ring Body Inspection		Dry	Air Condit	ioning
Under Carriage and Under Bonnet Inspection Comments					
				Electrical /	Access
					5
				Tail lights	
Interior Comments				Indicators	
Seats: Stains. Slight wear on drivers seat				Dashboard	warnin
Carnets: Good			Winers (fro	nt & ros	

	OK	Requires	NI/A
Engine	OK	Attention	N/A
Oil level	V		1
Smoke & fumes	1		
Engine performance			
Noise	<b>V</b>		
Coolant condition	V		
Cooling performance	•		
Radiator / Hoses (visual)	<b>/</b>		
Transmission		l I	1
Operation	<b>/</b>		
Noise	/		
Clutch	<u> </u>		
CV joints	/		
Wheel bearings			<u> </u>
Brakes		ı	
Performance	/		
Hand brake	<b>/</b>		
Tyres (lowest observed tread of	depth of	tyres)	
Left front		3	3.8 mm
Right front		3	3.5 mm
Left rear		5	5.9 mm
Right rear		6	6.2 mm
Spare	Yes		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	<b>/</b>		
Shock absorbers	<b>V</b>		
Air Conditioning / Heater			
Operation	<b>'</b>		
Electrical / Accessories			
Head lights	1		
Tail lights	V		
Indicators	~		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	~	1	
Window winder RL	1		
Window winder RR	1	1	
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			
Number of keys	1	1	
Central locking	1		1
Remote locking	-		<u> </u>
Sat. nav. (basic test only)	<u> </u>	<del>                                     </del>	
Reversing camera	-		<u> </u>
neversing carriera		ļ	

Road Condition	s During Test Drive	Dry		
Engine Timing N	Mechanism	Timing Chain		
Evidence of Can	n Belt Replacement	Yes	No	Kms
Inspected by:	Hoani Saunders			
Published by:	Mitch Chrystal			
Inspection Date:	18 Nov 2025			

have read and understood
this condition quide

Panels:

Dashboard:

**General Comments** 

Average Good

NΙΔ	MF	

SI	GN	IA.	TU	RF