

## **Basic Condition Guide**

Report ID:	27,795,688	Version:	1
Created:	22 Nov 2025		

Poquiroc


Make:	Toyota	Model:	Hiace
Body Style:	Van	Year:	2019
Rego No.:	MCJ850	Rego Expiry:	25 Jan 2026
WoF Expiry:	30 Apr 2026	Odometer:	82,533 Kms
Good No.:	27795688	VIN:	JTFHT02P605031980
Next Service:	89327	Service History:	Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack \*= Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Left taillight cracked

Left B pillar dented and scuffed

Right B pillar pin dented

Right rear sensor broken

Under Carriage and Under Ronnet Inspection Comments				
Conditions During Body Inspection	Dry			
Right rear sensor broken				

Engine oil leak

Radiator support panel surface rust

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

## General Comments

Partial service history

Road Conditions During Test Drive		Dry			
Engine Timing Mechanism		Cambelt			
	Evidence of Cam Belt Replacement		Yes	<b>V</b> No	Kms
	Inspected by:	Sione Mae			
	Published by:	Sione Mae			
	Inspection Date:	22 Nov 2025			

I have read and understood
this condition guido:

NAME			

	ОК	Attention	N/A
Engine			
Oil level	<b>/</b>		
Smoke & fumes	V V V		
Engine performance	<b>✓</b>		
Noise	/		
Coolant condition	<b>/</b>		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	/		
Noise	~		
Clutch			~
CV joints	<b>/</b>		
Wheel bearings	/		
Brakes			
Performance	<b>/</b>		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	•		7 mm
Right front			7 mm
Left rear			3 mm
Right rear			3 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	<b>/</b>		
Shock absorbers			
Air Conditioning / Heater			
Operation			
Electrical / Accessories			
Head lights			
Tail lights	<b>/</b>		
Indicators	<b>✓</b>		
Dashboard warning lights	<b>/</b>		
Wipers (front & rear)	·		
Window winder FL	·		
Window winder FR			
Window winder RL	·		
Window winder RR			
Rear view mirrors	· ·		
Radio (basic test only)	· /		
CD (basic test only)	· ·		
Number of keys	3	<u> </u>	
Central locking	·		
Remote locking	~		
Sat. nav. (basic test only)	*		/
Reversing camera	<b>/</b>		
g camera	-		

SIGNATURE			