

Basic Condition Guide

Report ID:	27,795,730	Version:	1
Created:	22 Nov 2025		

U	ntuet	S Bas	ic Condition Guide	Created: 22 Nov
Make:	Toyota	Model:	Hiace	
Body Style:	Van	Year:	2019	Fusins
Rego No.:	MCJ851	Rego Expiry:	25 Jan 2026	Engine
WoF Expiry:	08 May 2026	Odometer:	85,036 Kms	Oil level
Good No.:	27795730	VIN:	JTFHT02P100248642	Smoke & fumes
Next Service:		Service History:	No	Engine performance
Note: This report is	s not a warranty	,		Noise
This report is a guide diagnostic testing u	Coolant condition			
full mechanical insp	Cooling performance			
Key				Radiator / Hoses (visu
	R = Rust $C = C$			Transmission
D = Dent P	PT = Paint defect P = P	in dent SC = Sto	one Chips	Operation
SSC	Noise			
				Clutch
			W	CV joints
SC W				Wheel bearings
P	Brakes			
	Performance			
	Hand brake			
P	Tyres (lowest observ			
	Left front			
			S SC	Right front
DW	$\overline{}$		WR	Left rear
DW	Right rear			
Note: some defects	s and blemishes may not be	displayed in the diagr	am	Spare
Body Inspect	ion Comments			Suspension
Left B pillar pin	dented			Suspension perform
				Steering performance
				Shock absorbers
Conditions Du	ring Body Inspection		Dry	Air Conditioning / F
Under Carria	ge and Under Bonnet	Inspection Comn	nents	Operation
Underbody oxid	dation			Electrical / Accessor
				Head lights
				Tail lights
Interior Com	ments			Indicators
Seats:	Average			Dashboard warning
Carpets:	Average			Wipers (front & rear)
Panels:	Average			Window winder FL
Dashboard:	Average			Window winder FR
General Com	ments			Window winder RL
Flat 12 battery.				Window winder RR
				Rear view mirrors
				Radio (basic test only
Road Conditio	ons During Test Drive	Dry		CD (basic test only)
corranto	5	,		co (Subscreed of ity)

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	\(\tau \)		
Noise	V		
Coolant condition	~		
Cooling performance	/		
Radiator / Hoses (visual)	~		
Transmission			
Operation	✓		
Noise	~		
Clutch	/		
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	V		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		<u> </u>	6 mm
Right front			5 mm
Left rear			5 mm
Right rear			5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	1		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	3		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	1		
-			

I have read and understood this condition guide:

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 22 Nov 2025

Sione Mae

Sione Mae

NAME

Cambelt

Yes

✓ No

SIGNATURE

Kms