

Report ID:	27,796,090	Version:	3
Created:	26 Nov 2025		

		Doo!	a Candition Cuia	ما	ricport ib.	21,130,030	
V	nuel	S Basi	c Condition Guid	ie 	Created:	26 Nov 202	
Make:	Subaru	Model:	Impreza				
Body Style:	Hatchback	Year:	2010		Engine		
Rego No.:	LER756	Rego Expiry:	21 Jun 2026		Oil level		
WoF Expiry:	27 Nov 2026	Odometer:	176,486 Kms		Smoke & fu		
Good No.:	27796090	VIN:	7AT0GF09X1790360	8			
Next Service:	183000 kms	Service History:	No		Engine performance		
Note: This report is	not a warranty	,			Noise		
This report is a guide	only. Consideration is made		arts have not been dismantled or n from cold. The Vendor recomm		Coolant co		
	ection prior to purchase and			enus a	Cooling pe		
Key						Hoses (visual)	
	= Rust $C = C$			tscuffs	Transmissi	ion	
D = Dent PT	= Paint defect $P = Pi$	in dent SC = Sto	ne Chips		Operation		
D	D D P					Noise	
S					Clutch		
					CV joints		
					Wheel bearings		
					Brakes		
	Mr 11.				Performan	ce	
					Hand brake	2	
	8				Tyres (lowe	est observed t	
					Left front		
			(Q)	PT	Right front		
	\angle $\overline{}$ $\overline{}$				Left rear		
S D S P					Right rear		
Note: some defects and blemishes may not be displayed in the diagram					Spare		
Body Inspection	Body Inspection Comments				Suspensio	n	
					Suspension	n performanc	
					Steering pe	erformance	
					Shock abso	orbers	
Conditions Dur	ing Body Inspection		Dry		Air Condit	ioning / Hea	
Under Carriag	e and Under Bonnet	Inspection Comm	ents		Operation		

	O!′	Requires	N1/6
Engine	OK	Attention	N/A
Engine			1
Oil level	<i>y</i>		
Smoke & fumes			
Engine performance	<i>V</i>		
Noise			
Coolant condition	•		
Cooling performance	•		
Radiator / Hoses (visual)	<i>'</i>		
Transmission		I	
Operation	•		
Noise			
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes		ı	
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			6.0 mm
Right front			6.0 mm
Left rear			5.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	•		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	/		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	V		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	1	I.	
Central locking	1		1
Remote locking	·		
Sat. nav. (basic test only)	_		
Reversing camera			, , , , , , , , , , , , , , , , , , ,
neversing carriera		ļ	

	Seats:	G000			
	Carpets:	driver floor tear			
	Panels:	Average			
	Dashboard:	Good			
	General Comm	nents			
Road Conditions During Test Drive		Dry			
	Engine Timing Mechanism		Cambelt		
	Evidence of Cam Belt Replacement		Yes	∨ No	Kms
	Inspected by:	Fleoit Kumar			

I have read and understood this condition guide:

Inspection Date: 21 Nov 2025

Sam Huang

Published by:

Interior Comments

NAME

SIGNATURE